



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	21,050,466
Version:	1
Created:	25 Nov 2020

Make:	Lexus	Body Style:	Sedan
Model:	IS350	VIN:	7AT0B00HX20013136
Year:	2006	Odometer:	65,057 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	78	Under Carriage	Good		
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	79	Sun Roof Operation	•		
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		80	Front Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good	
5	Front Right Indicators	✓	34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good		
6	Front Left Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good		
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		84	Rear Wiper Blade	Good			
8	Rear Left Indicators	✓	37	CV Joints	✓ <td>61</td> <td>Left Front</td> <td>7.0 mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	61	Left Front	7.0 mm	85	R/H Mirror	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓ <td>62</td> <td>Right Front</td> <td>7.0 mm</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	62	Right Front	7.0 mm	86	L/H Mirror	Good		
10	Rear Reflectors	✓	39	Wheel Balance	✓ <td>63</td> <td>Left Rear</td> <td>7.0 mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	63	Left Rear	7.0 mm	87	L/F Guard	Good		
11	Hazard Lights	✓	40	Gearbox (Manual)	✓ <td>64</td> <td>Right Rear</td> <td>7.0 mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	64	Right Rear	7.0 mm	88	R/F Guard	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	Yes	89	L/H Doors	Good		
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	90	R/H Doors	Good		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior		67	AC Operation	✓	91	L/H Sill	Good
15	Number Plate Light	✓	Brakes		Interior		68	Heater Fan	✓	92	R/H Sill	Good	
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	69	Seatbelts	✓	93	Boot/Tail Gate	Good		
17	Speedo	✓	45	Rear Brakes	✓	70	Horn	✓	94	Front Bumper	Good		
18	Odometer	✓	46	Handbrake	✓	71	Seat Heaters	•	95	Rear Bumper	Good		
19	Rev Counter	✓	Keys and Locking		Interior		72	Sun Visors	✓	96	Roof	Good	
20	Fuel Gauge	✓	47	Central Locking	✓	73	Sun Visors Lights/Mirrors	✓	97	Bonnet	Good		
21	Wipers Front/Rear	✓	48	Remote Locking	✓	74	Seats	Average	98	Fuel Cap	✓		
22	Window Opener FL	✓	49	Number of Keys	2	75	Carpets	Average	99	Mud Flaps	✓		
23	Window Opener FR	✓	Engine		Interior		76	Panels	Average	100	WOF	✓	
24	Window Opener RL	✓	50	Oil Level	✓	77	Dashboard	Average					
25	Window Opener RR	✓	51	Smokes and Fumes	✓								
26	Rear View Mirrors	✓	52	Performance	✓								
27	Radio (Basic Test Only)	✓	53	Noise	✓								
28	CD (Basic Test Only)	✓	54	Starter Motor	✓								
29	Boot Open Switch	✓											

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	25 Nov 2020
I have read and understood this condition guide:			
Name:		Signature:	