

Report ID: 21,071,820 Version: 1 07 Dec 2020 Created:

Make:	Lexus	Model:	IS350	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	HWP333	Reg Expiry:	30 Jun 2021	Engine	1	l	
WoF Expiry:	17 Dec 2021	Odometer:	115,968 Kms	Good No:	21071820	Oil level	~		
VIN:	7AT0B00HX14005509	Next Service:	125962	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
			S SC S SC W		W	Performance	~		
Key:	LS	-0	S SC S SC W	-01-	VV	Radiator / Hoses (visual)	~		
S = scratch						Transmission	Transmission		
D = dent R = rust	sc d			715	SW	Operation	~		
PT = paint defe		F		$\left(\left \right\rangle \right)$		Noise	~		
C = crack				$+ \mathbf{\nabla}$	S SC W	Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	sc 916			- John		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	S		W			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Minor stone chips in the windscreen ,						Tyres (lowest observed tread	depth	of tyre	es)
						Left front 3 m			mm
						Right front	3	3	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbe							~		
	Air Conditioning / Heater								
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			CI			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Donovan Matara Date: 07 Dec 2020									
Date: 07 Dec 2020									

I have read and understood this condition guide.

Name:

Signature: