

Report ID: 21,100,042 Version: 1 11 Mar 2021 Created:

Make:	Subaru	Model:	Forester	Body Style:	SUV		Pass	Fail	N/A
Year:	2008	Registration:		Reg Expiry:		Engine	I	I	1
WoF Expiry:		Odometer:	95,903 Kms	Good No:	21100042	Oil level	~		
VIN:	7AT0GF17X20010400	Next Service:	100,868	Service Histor	r <b>y:</b> No	Smoke & fumes	~		
						Performance	~		+
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	been discontined or	Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	-		
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		+
S = scratch						Transmission			
D = dent R = rust	- HE			715	HIL	Operation	~		T
R = rust PT = paint def	ect NIP			$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				74114	CV joints	~		
* = decals	- Ole			-Jul-		Wheel bearings	~		
SC = stone chips						Brakes	•		<u> </u>
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be dis	blayed in the diagram	Hand Brake	~		+
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed tread	•	oftvre	L es)
						Left front 5 mi			
						Right front			mm
						Left rear		.5	mm
Conditio	as During Pody Inc	noction:	Dmr			Right rear		.5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories	<u> </u>		
Seats	Good					Head lights	~		1
	Cood					Tail lights	~		+
Carpets	Good					Indicators	~		+
Panels	Good					Dashboard warning lights	~		+
						Wipers (front & rear)	~		+
Dashboa	ord Good					Window winder FL	~		+
	1					Window winder FR	~		+
General Comments						Window winder RL	~		+
						Window winder RR	~		+
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	2	1	1
Road Conditions During Test Drive: Dry						Central locking	~		T
						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
							1	1	
Inspecte	d by: Bobby Zhong					Date: 11 Mar 20	21		

I have read and understood this condition guide.

Name: .....

Signature: .....