

Report ID: 21,102,258 Version: 1 14 Dec 2020 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:		Reg Expiry:	07 Feb 2021	Engine		-	<u> </u>
WoF Expiry:		Odometer:	170,834 Kms	Good No:	21102258	Oil level	~		
VIN:	JM0GH105100125526	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	D SC SC W		SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				The	BID SSCW	Operation	~		
R = rust				10	7HIX —	Noise	~		
PT = paint def C = crack	ect			+	SC W	Clutch	V		
P = pin dent	Ho	KI			JIII —				~
* = decals	- MIC			J.		CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			T
		Nata				Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		Ļ
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres)			
						Left front	3	8	mm
						Right front	3	8	mm
						Left rear	3	}	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
						Spare			
Under Ca	erriage & Under Bor	net Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ard					Window winder FL	~		<u> </u>
	ľ				J	Window winder FR	~		<u> </u>
General (<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		1
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		+
						Number of keys	2		L
Pood Car	ditions During Test					Central locking	2 V		
	ditions During Test		Dry			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			<i>v</i> <i>v</i>
	-1	•	- 1.1						L *
Inspected by: Donovan Matara Date: 14 Dec 2020									

I have read and understood this condition guide.

Name:

Signature: