


Report ID: 21,105,825

Version:

Make:	Great Wall	Model:	X200	Body Style:	SUV
Year:	2014	Registration:	HTR681	Reg Expiry:	26 Jan 2021
WoF Expiry:	28 Sep 2021	Odometer:	79,752 Kms	Good No:	21105825
VIN:	LGWFFEA51DB675700	Next Service:	89,000	Service History	/: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

Kms:

Inspected by:	Nathaniel Clark
---------------	-----------------

Created	ted: 23 Dec 2020				
	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	> > >				
Noise	~				
Cooling System	<u> </u>		1		
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	~				
Transmission			1		
Operation	~				
Noise	\(\times \)				
Clutch	~				
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed treac	l depth	of tyre	 es)		
Left front		.5	mm		
Right front		.5 .5	mm		
Left rear		.5 .5	mm		
Right rear		.0	mm		
Spare		Yes			
Suspension		103			
Suspension performance	~				
Steering performance	<i>y</i>				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	•/				
Tail lights	<i>y</i>				
Indicators	·/				
Dashboard warning lights	•				
Wipers (front & rear)	·/				
Window winder FL	> > > >				
Window winder FR	v				
Window winder RL					
Window winder RR	✓ ✓				
Rear view mirrors	•/				
Radio (basic test only)	V				
CD (basic test only)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
Number of keys			<u> </u>		
Central locking	1				
	V				
Remote locking	~				
Sat. Nav. (basic test only)					
Reversing camera			<u> </u>		
Date: 09 Dec 2020					

I have read and understood this condition guide.

Name:

Signature: