

Report ID: 21,109,416 Version: 1 18 Jan 2021 Created:

Make:	Nissan	Model:	Cefiro	Body Style:	Sedan		Pass	Fail	N/A
Year:	1999	<b>Registration:</b>	DGM153	<b>Reg Expiry:</b>	04 May 2021	Engine			
WoF Expiry:	18 Dec 2020	Odometer:	315,562 Kms	Good No:	21109416	Oil level	~		
VIN:	7A8DH2A0705053649	Next Service:	0	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc w s	-0	S SC W S SC W	-161-	S P SC W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SDSCW			715	S D C SC W	Operation	~		
R = rust PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack				+	S SC W	Clutch	•		~
P = pin dent					741L	CV joints	~		
* = decals	SDSCW 918			- NL	S SC W	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs S SC W						Performance	~		
		Note: son	ne defects & blemishes	s may not be disi	blaved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		oftvre	
RR tail light broken ,						Left front 3 mm			
						Right front		, 1	mm
						Left rear			mm
						Right rear	2 mm 3 mm		
Conditions During Body Inspection: Dry						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
		•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
						Operation		~	
Interior Comments						Electrical / Accessories		V	
Contr	wear and t	ear,minor stains	1			Head lights	~		
Seats						Tail lights	-		<u> </u>
Carpets	wear and t	ear,minor stains	,				<b>v</b>		<sup> </sup>
	Average						<b>v</b>		
Panels	-					Dashboard warning lights	V 		
Dashboa	rd broken lid	top of dash,top	of dash cracked ,			Wipers (front & rear) Window winder FL	<b>v</b>		<sup> </sup>
							<b>v</b>		<sup> </sup>
General C	Comments					Window winder FR Window winder RL	<b>v</b>		<sup> </sup>
							~		<sup> </sup>
						Window winder RR Rear view mirrors	V		
							~		<sup> </sup>
						Radio (basic test only)	V		<sup> </sup>
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
Engine Tir	ning Mechanism:	Timing (				Remote locking		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
LVIGENCE				11113.		Reversing camera			~
Inspected	d by: Donovan Matara	a				Date: 18 Jan 202	21		

I have read and understood this condition guide.

Name: .....

Signature: .....