

Report ID: 21,110,631 Version: 1 12 Jan 2021 Created:

Make:	Holden	Model:	Commodore	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2014	Registration:	HMK886	Reg Expiry:	11 Feb 2021	Engine	1		I	
WoF Expiry:	28 Dec 2021	Odometer:	227,263 Kms	Good No:	21110631	Oil level	~			
VIN:	6G1FB8E39EL966192	Next Service:	237214	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	~			
Key:	sc	-0				Radiator / Hoses (visual)	~			
S = scratch						Transmission	•			
D = dent SC W SD W						Operation	~			
R = rust				1 M	JHIH	Noise	~			
PT = paint def C = crack				+	P SC	Clutch	V		~	
P = pin dent	Ho					CV joints	~			
* = decals D SC D D						Wheel bearings	~			
SC = stone chips							5			
W = significant scuffs SC W P SC W D W						Brakes Performance				
	Je w	Nata					~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<u>.</u>		
Minor stone chips in the windscreen ,LF door mirror casing cracked ,						Tyres (lowest observed tread depth of tyres)				
						Left front		3	mm	
						Right front	3 mm		mm	
						Left rear	3 mm		mm	
Conditions During Body Inspection: Dry						Right rear	3 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
Steering performance							~			
Shock absorbers							~			
	Air Conditioning / Heater									
						Operation		~		
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	panels mis	ssing rear and mi	ddle console,			Dashboard warning lights	~			
	. modified t	op of dash panel,				Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		L	
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)							-		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera		V		
L										
Inspected by: Donovan Matara Date: 12 Jan 2021										

I have read and understood this condition guide.

Name:

Signature: