



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	21,124,355
Version:	1
Created:	10 Feb 2021

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	VIN:	7AT0GF09X21008713
Year:	2012	Odometer:	141,362 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good				
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation	•		
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good		
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓	82	Side Windows (no chips)	Good	
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83	Front Wiper Blades	Good		
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good		
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	5	mm		
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	6	mm	63	Left Rear	5	mm
9	Reversing Lights	✓	38	Wheel Bearing	✓	64	Right Rear	5	mm	65	Spare	N/A	
10	Rear Reflectors	✓	39	Wheel Balance	✓	66	Tools	✓	67	AC Operation	✓		
11	Hazard Lights	✓	40	Gearbox (Manual)	• <td>68</td> <td>Heater Fan</td> <th>✓</th> <td>69</td> <td>Seatbelts</td> <th>✓</th>	68	Heater Fan	✓	69	Seatbelts	✓		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	70	Horn	✓	71	Seat Heaters	•		
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		74	Seats	Good	75	Carpets	Good		
15	Number Plate Light	✓	Brakes		Interior		76	Panels	Good	77	Dashboard	Good	
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	67	AC Operation	✓	78	Under Carriage	Good		
17	Speedo	✓	45	Rear Brakes	✓	68	Heater Fan	✓	79	Sun Roof Operation	•		
18	Odometer	✓	46	Handbrake	✓	69	Seatbelts	✓	80	Front Windscreen (no chips)	Good		
19	Rev Counter	✓	Keys and Locking		70	Horn	✓	81	Back Windscreen (no chips)	Good			
20	Fuel Gauge	✓	47	Central Locking	✓	71	Seat Heaters	•	82	Side Windows (no chips)	Good		
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	83	Front Wiper Blades	Good		
22	Window Opener FL	✓	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	✓	84	Rear Wiper Blade	Good		
23	Window Opener FR	✓	Engine		74	Seats	Good	85	R/H Mirror	Good			
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Good	86	L/H Mirror	Good		
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Good	87	L/F Guard	Good		
26	Rear View Mirrors	✓	52	Performance	✓	77	Dashboard	Good	88	R/F Guard	Good		
27	Radio (Basic Test Only)	✓	53	Noise	✓	<div>Turners Certification Key:</div> <div>✓ = Pass</div> <div>✗ = Fail</div> <div>• = Not applicable for this vehicle</div>							
28	CD (Basic Test Only)	✓	54	Starter Motor	✓								
29	Boot Open Switch	✓											

Inspected by:	Lewis Dolamore	Date:	10 Feb 2021
I have read and understood this condition guide:			
Name:		Signature:	