



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	21,138,027
Version:	1
Created:	07 Apr 2021

Make:	Mitsubishi	Body Style:	Hatchback
Model:	Galant	VIN:	7AT0CJ0JX21000230
Year:	2011	Odometer:	87,187 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	Exterior		
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79	Sun Roof Operation	•	
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good	
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	
4	High Stop Light	✓	Transmission and Drive			Suspension			82	Side Windows (no chips)	Good	
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good	
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good	
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	Wheels and Tyres			
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	5	mm	86	L/H Mirror	Good
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	5	mm	87	L/F Guard	Good
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	5	mm	88	R/F Guard	Good
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	5	mm	89	L/H Doors	Good
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	Yes	90	R/H Doors	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	91	L/H Sill	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior			92	R/H Sill	Good	
15	Number Plate Light	✓	Brakes			67	AC Operation	✓	93	Boot/Tail Gate	Good	
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	94	Front Bumper	Good	
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	95	Rear Bumper	Good	
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	96	Roof	Good	
19	Rev Counter	✓	Keys and Locking			71	Seat Heaters	•	97	Bonnet	Good	
20	Fuel Gauge	✓	47	Central Locking	✓	72	Sun Visors	✓	98	Fuel Cap	✓	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	99	Mud Flaps	✓	
22	Window Opener FL	✓	49	Number of Keys	2	74	Seats	Good	100	WOF	✓	
23	Window Opener FR	✓	Engine			75	Carpets	Good	Turners Certification Key: ✓ = Pass ✗ = Fail • = Not applicable for this vehicle			
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Good				
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Good				
26	Rear View Mirrors	✓	52	Performance	✓							
27	Radio (Basic Test Only)	✓	53	Noise	✓							
28	CD (Basic Test Only)	✓	54	Starter Motor	✓							
29	Boot Open Switch	✓										

Inspected by:	Bobby Zhong	Date:	07 Apr 2021
I have read and understood this condition guide:			
Name:		Signature:	