

Report ID: 21,259,642


Version: 1

Created: 19 Apr 2024

Make:	Toyota	Model:	Hilux	Body Style:	Utility
Year:	2018	Registration:	LTN958	Reg Expiry:	22 May 2024
WoF Expiry:	16 Apr 2025	Odometer:	70,563 Kms	Good No:	21259642
VIN:	MR0HA3CD90042252	Next Service:	79000kms	Service Histor	y: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Has Beacon fitted to roof

Conditions Du	rina Bodv	Inspection:	Drv

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Timing Chain Engine Timing Mechanism:

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Lindsay Malpas Date: 27 Mar 2024

Name:

Cooling System Coolant condition			
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings	ν ν		
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings	ν ν		· ·
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings	ν ν		· ·
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings	ν ν		· ·
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			·
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings			·
Transmission Operation Noise Clutch CV joints Wheel bearings	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		· ·
Transmission Operation Noise Clutch CV joints Wheel bearings	\ \ \ \ \ \		· ·
Operation Noise Clutch CV joints Wheel bearings	\ \ \ \		·
Noise Clutch CV joints Wheel bearings	\ \ \ \ \		v
Clutch CV joints Wheel bearings	ン ン ン		~
CV joints Wheel bearings	у У		~
Wheel bearings	ν ν		
	'		1
Brakes			
i			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread o	depth	of tyre	<u>-</u> s)
Left front	7.	.3	mm
Right front	8.	.3	mm
Left rear	rear 9.2		mm
Right rear	8.	.0	mm
Spare		Yes	
Suspension			
Suspension performance	'		
Steering performance	~		
Shock absorbers	'		
Air Conditioning / Heater			
Operation	'		
Electrical / Accessories			
Head lights	'		
Tail lights	'		
Indicators	'		
Dashboard warning lights	'		
Wipers (front & rear)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder FL	'		
Window winder FR	'		
Window winder RL	'		
Window winder RR	'		
Rear view mirrors	~		
Radio (basic test only)	'		
CD (basic test only)			~
Number of keys	4		
Central locking	'		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	'		

Signature: