

Basic Vehicle Condition Guide

Report ID: 21,264,059


Version:

Created: 19 Apr 2025

Make: Model: Mazda CX-8 **Body Style:** SUV Year: 2021 Registration: NNL441 Reg Expiry: 03 Jun 2025 WoF Expiry: **Odometer: Good No:** 22 May 2025 74,193 Kms 21264059 **Next Service:** VIN: JM0KG4W2A00350657 81600kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Crack in Windscreen. Rear Air Vent damaged Remote Key damaged

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Lindsay Malpas Date: 17 Apr 2025

Name:

| | Pass | Fail | N/A | |
|------------------------------|---|---------|----------|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>y y</i> | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | • | | | |
| Operation | ~ | | | |
| Noise | V | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 3.0 | | mm | |
| Right front | 3.2 | | mm | |
| Left rear | 3.4 | | mm | |
| Right rear | 3.1 | | mm | |
| Spare | Yes | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | \(\triangle \) | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | ı | | ı | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \(\times \) | | | |
| Window winder FL | ~ | | | |
| Window winder FR | VVV | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | l | <u> </u> | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | ~ | | | |
| Reversing camera | · | | | |
| | | | | |

Signature: