

Basic Vehicle Condition Guide

Report ID: 21,264,435

Pass

1

/

/

V

1

5.2

5.5

2.6

2.0

1

/

/

/

1

2

1

Yes

Version:

Engine

Oil level

Noise

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of kevs

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Smoke & fumes

Performance

Cooling System

Coolant condition

14 Mar 2025 Created:

Fail

N/A

1

mm

mm


mm

mm

Make: Model: Holden Colorado **Body Style:** Utility Year: 2019 Registration: PFD318 **Reg Expiry:** 18 May 2025 WoF Expiry: **Odometer:** 09 Feb 2026 59,647 Kms **Good No:** 21264435 VIN: MMU148MK0LH618114 **Next Service:** 66500kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Inspected by:

No Handbook or Service Record

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Lindsay Malpas

I have read and understood this condition guide.

	Central locking		
	Remote locking	V	
	Sat. Nav. (basic test only)	V	
Kms:	Reversing camera	V	
Date: 14 Mar 2025			
Name: Signature:			