

Report ID: 21,390,879 Version: 5 03 Oct 2022 Created:

Signature: .....

Make:	Maserati	Model:	Granturismo	Body Style:	Sports Car		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>	LDQ123	Reg Expiry:	06 Jan 2023	Engine	1	L	
WoF Expiry:	29 Sep 2023	Odometer:	70,743 Kms	Good No:	21390879	Oil level	~		
VIN:	ZAMLH45C00006494(	Next Service:	unknown	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
		_				Performance	~		
Key:	PT	-0	P W		W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation	~		
R = rust PT = paint def				$\prod$	JHH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints			~
* = decals	sc 916			- NL	EITR	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	s may not be disr	blayed in the diagram	Hand Brake	~		
· · ·	pection Comments	1010.501		s may not be alsp	nayea in the diagram	Tyres (lowest observed tread	•	oftyre	) )
Front number plate is inside car.						Left front 3.5 mm			
						Right front			mm
						Left rear	3.		mm
			_			Right rear	3.		-
Conditions During Body Inspection: Dry						Spare	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare N/A Suspension			
	under car bent.	ince inspectie	<u>eennents</u>			-			
	under eur bent.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Average					Indicators	~		
Panels	//veruge					Dashboard warning lights	~		
Dashboa	Good, stee	ering wheel worr	۱.			Wipers (front & rear)	~		
	-					Window winder FL	~		
General	<u>Comments</u>					Window winder FR	~		
						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Enging Ti	ming Machanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
	or Cam Bert Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Blair Robertson Date: 12 Jul 2021									

I have read and understood this condition guide.

Name: .....