

Report ID: 21,409,483 Version: 1 23 Apr 2024 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JLZ127	Reg Expiry:	24 May 2024	Engine			L
WoF Expiry:	03 Nov 2024	Odometer:	259,428 Kms	Good No:	21409483	Oil level	~		
VIN:	MNAUMFF50FW4939(	Next Service:	270000kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SP	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC D D W W						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				74114	CV joints	~		
* = decals	PSC 916			-No-	AD DW	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S P S P S P S P						Performance	~		
Bodylper		Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
Drivers seat torn. Screw holes in centre console						Left front	8.3 mm		
Bonnet stru	ts not working					Right front	9.		mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear	5.		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor surface rust.						Suspension performance	~		
Minor dent	s in right sill					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	11		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	All plastic	average condition	าก			Tail lights	~		
Carpets	, in plastic,	average condition				Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments					Window winder RL	~			
Has Beacon fitted to canopy roof, and GPS aerial to main roof						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	<b>v</b>		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Lindsay Malpas Date: 09 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....