

Report ID: 21,409,580 Version: 1 23 Apr 2024 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	<b>Registration:</b>	LWR380	<b>Reg Expiry:</b>	26 May 2024	Engine			
WoF Expiry:	18 Apr 2024	Odometer:	129,297 Kms	Good No:	21409580	Oil level	~		
VIN:	MMAJLKL10KH003277	Next Service:	141000kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged to	r an additional c	narge.	Coolant condition	~		
			SP SP		D	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	w AR			210	BILDW	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					S P SC	Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals	sc 916			The second	FID SP	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	t scuffs S		P SP		SP	Performance	~		
Body Incr	Position Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Drivers seat torn.						Tyres (lowest observed tread depth of tyres)			es)
Cuts in centre rear seat.						Left front 5.1 mn			mm
Left wing mirror housing broken.						Right front	5.	.0	mm
Right tail light cracked Tonneau cover hold down fittings missing from tailgate						Left rear		2.7 m	
Conditions During Body Inspection: Dry						Right rear	2.6 mm		mm
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		·
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	All					Tail lights	~		
Carpets	All plastic					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Noisy drive	belt					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		Ľ –
Road Conditions During Test Drive: Dry						Central locking	2		
Koad Con	ations During Test	Drive:	Dry			Remote locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	-		~
-	of Cam Belt Replac	-	lot Applicable	Kms:		Reversing camera	~		~
							~		
Inspected by: Lindsay Malpas Date: 04 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....