

Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	21,472,502
Version:	1
Created:	22 Mar 2021

Make:	Subaru	Body Style:	Wagon
Model:	Legacy	VIN:	7AT0GF0BX21008985
Year:	2009	Odometer:	111,292 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release		Coc	oling System			Exte	erior	
1	Battery	31	Reversing Camera		55	Coolant Condition			78	Under Carriage	Good
2	Headlights	32	USB Port •		56	Performance			79	Sun Roof Operation	•
3	Tail Lights	33	Window Lock Swi	tch	57	Radiator/Hoses (visual)			80	Front Windscreen (no chips)	Good
4	High Stop Light	Tra	nsmission and D	rive	Sus	Suspension			81	Back Windscreen (no chips)	Good
5	Front Right Indicators	34	Operation		58	Suspension Performance			82	Side Windows (no chips)	Good
6	Front Left Indicators	35	Noise		59	Steering Performance			83	Front Wiper Blades	Good
7	Rear Right Indicators	36	Clutch	•	60	Shock Absorbers			84	Rear Wiper Blade	Good
8	Rear Left Indicators	37	CV Joints		Wh	neels and Tyres			85	R/H Mirror	Good
9	Reversing Lights	38	Wheel Bearing		61	Left Front	6 n	nm	86	L/H Mirror	Good
10	Rear Reflectors	39	Wheel Balance		62	Right Front	6 n	nm	87	L/F Guard	Good
11	Hazard Lights	40	Gearbox (Manual)	•	63	Left Rear	6 n	nm	88	R/F Guard	Good
12	Courtesy Lights	41	Engine Timing	Cambelt	64	Right Rear	6 n	nm	89	L/H Doors	Good
13	Dashboard Lights	42	Evidence of Cam Belt Replacement	Yes	65	Spare	Yes	_	90	R/H Doors	Good
14	Dashboard Dimmer Switch	43	Replaced at (odometer reading)	90,448	66	Tools			91	L/H Sill	Good
15	Number Plate Light	Bra	ıkes		Inte	nterior			92	R/H Sill	Good
16	Dashboard Warning Lights	44	Front Brakes		67	AC Operation			93	Boot/Tail Gate	Good
17	Speedo	45	Rear Brakes	ar Brakes 68 Heater Fan		94	Front Bumper	Good			
18	Odometer	46	Handbrake		69	Seatbelts		95	Rear Bumper	Good	
19	Rev Counter	Key	s and Locking	4	70	Horn		96	Roof	Good	
20	Fuel Gauge	47	Central Locking		71	Seat Heaters			97	Bonnet	Good
21	Wipers Front/Rear	48	Remote Locking		72	Sun Visors 💆			98	Fuel Cap	
22	Window Opener FL	49	Number of Keys	1	73	Sun Visors Lights/Mirrors			99	Mud Flaps	
23	Window Opener FR	Eng	gine		74	Seats	Good		100	WOF	
24	Window Opener RL	50	Oil Level		75	Carpets	Good				
25	Window Opener RR	51	Smokes and Fume	es	76	Panels	Good				
26	Rear View Mirrors	52	Performance		77	Dashboard	Good				
27	Radio (Basic Test Only)	53	Noise							ers Certification K	ey:
28	CD (Basic Test Only)	54	Starter Motor						√= F ×= F		
29	Boot Open Switch				1					^{बा।} lot applicable for thi	s vehicle

Inspected by:	Lewis Dolamore	Date:	22 Mar 2021					
I have read and understood this condition guide:								
Name:		Signature:						