

Coolant condition V Radiator / Hoses (visual) V V V V P = pin dent CV joints ~ S SC * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs SC SC SC Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 4.0 **Right front** 4.0 mm Left rear 3.0 mm **Right rear** 3.0 mm Conditions During Body Inspection: Dry Spare N/A Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Good Head lights Seats 1 Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Nice car, drives well Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) ~ Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism:** Unknown Sat. Nav. (basic test only) ~ Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera 1

Inspected by: Donovan Matara

Date: 06 Apr 2021

I have read and understood this condition guide.

Name:

Signature:

Report ID: 21,509,391 Version: 2 Created: 04 Jun 2021

Pass

~

V

V

~

N/A

Fail