

Report ID: 21,832,352 Version: 1 03 May 2021 Created:

Make:	Mini	Model:	Cooper	Body Style:	Convertible		Pass	Fail	N/A
Year:	2004	Registration:		Reg Expiry:	01 Sep 2021	Engine	1		
WoF Expiry:	18 Dec 2021	Odometer:	154,377 Kms	Good No:	21832352	Oil level	~		
VIN:	WMWRF32020TF5220	Next Service:	157000	Service Histor	y: No	Smoke & fumes	~		
				· · · · · · · · · · · · · · · · · · ·		Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
					W	Performance	~		
Key:	S	-0	<u>s</u>		V	Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	s sc			715	HILW	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	V		
C = crack						Clutch	~		
P = pin dent	LIDE HID				74 <u>11</u> 4	CV joints	V		
* = decals	SDSC 91			The second		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S P W						Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front 1.5			mm	
						Right front	2.0 mn		mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry					Right rear	2.5 mm		mm	
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Oil at minin	num					Suspension performance	~		
Oil leaks Both front t	yres worn inside edges					Steering performance	r		
Rf shock minor leak						Shock absorbers		~	
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories	1		1
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1				I	Window winder FR	~		
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry									
			-			Remote locking	~	~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Nathaniel Clark Date: 20 Apr 2021									

I have read and understood this condition guide.

Name:

Signature: