



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	21,845,073
Version:	1
Created:	04 Jun 2021

Make:	Mazda	Body Style:	Sedan
Model:	Atenza	VIN:	7AT0C139X21200077
Year:	2015	Odometer:	104,572 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good					
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•							
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good								
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	81	Back Windscreen (no chips)	Good						
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	82	Side Windows (no chips)	Good						
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	83	Front Wiper Blades	Good								
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	4	mm	84	Rear Wiper Blade	Good					
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	4.5	mm	63	Left Rear	2.5	mm	85	R/H Mirror	Good			
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	64	Right Rear	3.5	mm	65	Spare	N/A	86	L/H Mirror	Good				
9	Reversing Lights	✓	39	Wheel Balance	✓	66	Tools	✓	87	L/F Guard	Good								
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	88	R/F Guard	Good						
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓	69	Seatbelts	✓	89	L/H Doors	Good					
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓	71	Seat Heaters	•	90	R/H Doors	Good					
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	91	L/H Sill	Good					
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	74	Seats	Good	75	Carpets	Good	92	R/H Sill	Good			
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	76	Panels	Good	77	Dashboard	Good	93	Boot/Tail Gate	Good		
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	78	Seats	Good	79	Carpets	Good	94	Front Bumper	Good			
17	Speedo	✓	48	Remote Locking	✓	49	Number of Keys	1	80	Seats	Good	81	Carpets	Good	95	Rear Bumper	Good		
18	Odometer	✓	Engine		50	Oil Level	✓	82	Seats	Good	83	Panels	Good	96	Roof	Good			
19	Rev Counter	✓	51	Smokes and Fumes	✓	52	Performance	✓	84	Seats	Good	85	Panels	Good	97	Bonnet	Good		
20	Fuel Gauge	✓	53	Noise	✓	54	Starter Motor	✓	86	Seats	Good	87	Panels	Good	98	Fuel Cap	✓		
21	Wipers Front/Rear	✓							88	Seats	Good	89	Panels	Good	99	Mud Flaps	✓		
22	Window Opener FL	✓							89	Seats	Good	90	Panels	Good	100	WOF	✓		
23	Window Opener FR	✓							90	Seats	Good								
24	Window Opener RL	✓							91	Seats	Good								
25	Window Opener RR	✓							92	Seats	Good								
26	Rear View Mirrors	✓							93	Seats	Good								
27	Radio (Basic Test Only)	✓							94	Seats	Good								
28	CD (Basic Test Only)	✓							95	Seats	Good								
29	Boot Open Switch	✓							96	Seats	Good								

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

#### Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Dean Sinclair	Date:	04 Jun 2021
---------------	---------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--