

Basic Vehicle Condition Guide

Report ID: 22,011,067


Version: 1

Created: 16 Sep 2021

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2009 Registration: FCP137 Reg Expiry: 10 Feb 2022 **WoF Expiry: Odometer: Good No:** 12 Jul 2022 190,358 Kms 22011067 VIN: **Next Service:** KL3CD26RJ9B536797 200000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled o diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommend a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Average | | | |
| Dashboard | Good | | | |

General Comments

Chips in windscreen

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

I have read and understood this condition guide.

Kms:

Inspected by: Nathaniel Clark Date: 29 Jul 2021

Name:

| | | Pass | Fail | N/A | | | |
|--------|--|-----------------|------|-----|--|--|--|
| | Engine | | | | | | |
| | Oil level | ~ | | | | | |
| | Smoke & fumes | ~ | | | | | |
| | Performance | \(\times \) | | | | | |
| or | Noise | ~ | | | | | |
| ls | Cooling System | | | • | | | |
| | Coolant condition | ~ | | | | | |
| | Performance | ~ | | | | | |
| | Radiator / Hoses (visual) | ~ | | | | | |
| _ | Transmission | | | | | | |
| ╝ | Operation | ~ | | | | | |
| _ | Noise | ~ | | | | | |
| _ | Clutch | | | ~ | | | |
| | CV joints | ~ | | | | | |
| | Wheel bearings | ~ | | | | | |
| | Brakes | | | | | | |
| | Performance | ~ | | | | | |
| n | Hand Brake | ~ | | | | | |
| | Tyres (lowest observed tread depth of tyres) | | | | | | |
| | Left front | 4 | .0 | mm | | | |
| | Right front | 4 | .0 | mm | | | |
| | Left rear | 2.5 | | mm | | | |
| | Right rear | 5 | .0 | mm | | | |
| 믁 | Spare | N/A | | | | | |
| | Suspension | | | | | | |
| | Suspension performance | ~ | | | | | |
| | Steering performance | ~ | | | | | |
| | Shock absorbers | ~ | | | | | |
| | Air Conditioning / Heater | | | • | | | |
| 〓 | Operation | ~ | | | | | |
| | Electrical / Accessories | • | | • | | | |
| | Head lights | ~ | | | | | |
| | Tail lights | V | | | | | |
| | Indicators | ~ | | | | | |
| | Dashboard warning lights | \(\triangle \) | | | | | |
| | Wipers (front & rear) | ~ | | | | | |
| | Window winder FL | ~ | | | | | |
| ヿ | Window winder FR | ~ | | | | | |
| | Window winder RL | ~ | | | | | |
| | Window winder RR | ~ | | | | | |
| | Rear view mirrors | ~ | | | | | |
| | Radio (basic test only) | ~ | | | | | |
| | CD (basic test only) | ~ | | | | | |
| Ш | Number of keys | 2 | | | | | |
| \Box | Central locking | ~ | | | | | |
| 닉 | Remote locking | ~ | | | | | |
| | Sat. Nav. (basic test only) | | | ~ | | | |
| | Reversing camera | ~ | | | | | |
| | Date: 20 Iul 202 | 1 | | | | | |
| | Date: 29 Jul 202 | 1 | | | | | |

Signature: