



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	22,037,841
Version:	2
Created:	12 Oct 2021

Make:	Mercedes-Benz	Body Style:	Hatchback
Model:	B180	VIN:	WDD2462422J062127
Year:	2012	Odometer:	72,910 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good													
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good													
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good													
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good											
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good											
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		87	L/F Guard	Good	88	R/F Guard	Good											
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	5.0	mm	62	Right Front	5.0	mm	89	L/H Doors	Good											
7	Rear Right Indicators	✓	37	CV Joints	✓	63	Left Rear	6.0	mm	64	Right Rear	6.0	mm	90	R/H Doors	Good											
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	Interior		65	Spare	N/A	66	Tools	✓	91	L/H Sill	Good											
9	Reversing Lights	✓	39	Wheel Balance	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	92	R/H Sill	Good										
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	93	Boot/Tail Gate	Good										
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	94	Front Bumper	Good										
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	76	Panels	Good	77	Dashboard	Good	96	Roof	Good	95	Rear Bumper	Good										
13	Dashboard Lights	✓	43	Replaced at (odometer reading)								97	Bonnet	Good	98	Fuel Cap	✓										
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	45	Rear Brakes	✓	46	Handbrake	✓	Keys and Locking		47	Central Locking	✓									
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	Keys and Locking		47	Central Locking	✓	48	Remote Locking	✓	49	Number of Keys	2								
16	Dashboard Warning Lights	✓	46	Handbrake	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓								
17	Speedo	✓	Keys and Locking		47	Central Locking	✓	48	Remote Locking	✓	49	Number of Keys	2	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓						
18	Odometer	✓	48	Remote Locking	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Smokes and Fumes	✓	56	Performance	✓							
19	Rev Counter	✓	49	Number of Keys	2	53	Noise	✓	54	Starter Motor	✓				57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓							
20	Fuel Gauge	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓					
21	Wipers Front/Rear	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓				
22	Window Opener FL	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓				
23	Window Opener FR	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓				
24	Window Opener RL	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓				
25	Window Opener RR	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓				
26	Rear View Mirrors	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm			
27	Radio (Basic Test Only)	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm		
28	CD (Basic Test Only)	•	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm	63	Left Rear	6.0	mm	
29	Boot Open Switch	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm	63	Left Rear	6.0	mm	64	Right Rear	6.0	mm

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

#### Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	29 Sep 2021
---------------	---------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--