



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	22,172,241
Version:	1
Created:	25 Jan 2022

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	VIN:	7AT0GF09X22022137
Year:	2012	Odometer:	143,049 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good	
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good		
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good		
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good		
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7	mm	86	L/H Mirror	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	7	mm	87	L/F Guard	Good			
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	7	mm	88	R/F Guard	Good			
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>7</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	7	mm	89	L/H Doors	Good			
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	N/A	66	Tools	✓	90	R/H Doors	Good	
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	Not Applicable		Interior		67	AC Operation	✓	91	L/H Sill	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	43					Replaced at (odometer reading)	68	Heater Fan	✓	92	R/H Sill
13	Dashboard Lights	✓	44	Front Brakes	✓			69	Seatbelts	✓	93	Boot/Tail Gate	Good		
14	Dashboard Dimmer Switch	✓	45	Rear Brakes	✓	Keys and Locking		70	Horn	✓	94	Front Bumper	Good		
15	Number Plate Light	✓	46	Handbrake	✓	47	Central Locking	✓	71	Seat Heaters	•	95	Rear Bumper	Good	
16	Dashboard Warning Lights	✓	Brakes		48	Remote Locking	✓	72	Sun Visors	✓	96	Roof	Good		
17	Speedo	✓	49	Number of Keys	1	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	✓	97	Bonnet	Good	
18	Odometer	✓	Keys and Locking		Engine		74	Seats	Good	98	Fuel Cap	✓			
19	Rev Counter	✓	50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td>99</td><td>Mud Flaps</td><th>✓</th></th>	51	Smokes and Fumes	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	75	Carpets	Good	99	Mud Flaps	✓	
20	Fuel Gauge	✓	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓</th> <td>76</td> <td>Panels</td> <td>Good</td> <td>100</td> <td>WOF</td> <th>✓</th>	53	Noise	✓	76	Panels	Good	100	WOF	✓	
21	Wipers Front/Rear	✓	54	Starter Motor	✓ <td colspan="2"></td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td colspan="3"></td>			77	Dashboard	Good					
22	Window Opener FL	✓													
23	Window Opener FR	✓													
24	Window Opener RL	✓													
25	Window Opener RR	✓													
26	Rear View Mirrors	✓													
27	Radio (Basic Test Only)	✓													
28	CD (Basic Test Only)	✓													
29	Boot Open Switch	✓													

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Dean Sinclair	Date:	25 Jan 2022
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--