

Report ID: 22,191,512 Version: 1 02 Feb 2022 Created:

Make:	Lexus	Model:	LS460	Body Style:	Sedan	1[Pass	Fail	N/A		
Year:	2007 Registration: Reg Expiry:				Engine							
WoF Expiry:	21 Jan 2023	Odometer:	116,257 Kms	Good No:	22191512	١ŀ	Oil level	~				
VIN:	7AT0B00JX22019507	Next Service:	126250	Service Histor	r y: No	lf	Smoke & fumes	~				
						iľ	Performance	~				
	port is not a warranty	eration is made	for age and mileage	Parts have not	t been dismantled or	lt	Noise	~				
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System					
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	lŀ	Coolant condition	~				
						۱ŀ	Performance	~				
Key:		-0		-161-		lŀ	Radiator / Hoses (visual)	~				
S = scratch						ļŀ	Transmission					
D = dent R = rust				715	HIL	lŀ	Operation	~				
PT = paint def		F I		$\left(\left \right\rangle \right)$		lŀ	Noise	~				
C = crack				+		ŀ	Clutch			~		
P = pin dent	HIG				7411	lŀ	CV joints	~				
* = decals	- Ole			The		lŀ	Wheel bearings	~				
SC = stone chips						Brakes						
W = significant scuffs						ļŀ	Performance	~				
Dadutie	action Comments	Note: son	ne defects & blemishes	s may not be dis	blayed in the diagram		Hand Brake	· ·				
Body Inspection Comments						ļŀ	Tyres (lowest observed tread	•	of tyre	es)		
						lŀ	Left front		5	mm		
						lŀ	Right front		5	mm		
						Jŀ	Left rear		5	mm		
Conditio	as During Body Ins	nection:	Day			۱ŀ	Right rear		5	mm		
Conditions During Body Inspection: Dry						┚┝	Spare Yes					
Under Carriage & Under Bonnet Inspection Comments							Suspension		105			
Rear wheel drive						lŀ	Suspension performance	~				
						lŀ	Steering performance	~				
							Shock absorbers	~				
							Air Conditioning / Heater					
						ļŀ	Operation	~				
Interior Comments						lŀ	Electrical / Accessories					
Seats	Good					lŀ	Head lights	~				
	Cood					lŀ	Tail lights	~				
Carpets	Good						Indicators	· ·				
Panels	Good						Dashboard warning lights	~				
						lŀ	Wipers (front & rear)	· ·				
Dashboa	rd Good						Window winder FL	V				
	I					ļŀ	Window winder FR	~				
General C	<u>Comments</u>						Window winder RL	~				
No puzzle nut on wheels							Window winder RR	~				
						lŀ	Rear view mirrors	~				
							Radio (basic test only)	~				
							CD (basic test only)	~				
						Jŀ	Number of keys	1	1	1		
Road Conditions During Test Drive: Dry						۱ŀ	Central locking	~				
						ļŀ	Remote locking	~				
Engine Ti	ming Mechanism:	Timing (Chain				Sat. Nav. (basic test only)			~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						lŀ	Reversing camera	~		-		
Inspected by: Takaya Murayama Date: 02 Feb 2022												

I have read and understood this condition guide.

Name: