



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	22,222,471
Version:	1
Created:	06 Apr 2022

Make:	Audi	Body Style:	SUV
Model:	Q5	VIN:	WAUZZZ8R09A033105
Year:	2009	Odometer:	88,292 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	8	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>8</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	8	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>8</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	8	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>8</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	8	mm	89	L/H Doors	Good		
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	Yes	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67	AC Operation	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good	
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	69	Seatbelts	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>70</td> <td>Horn</td> <th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th>	70	Horn	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td>	94	Front Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>71</td><td>Seat Heaters</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	46	Handbrake	✓ <td>71</td> <td>Seat Heaters</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	71	Seat Heaters	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>96</td><td>Roof</td><td>Good</td></th>	72	Sun Visors	✓ <td>96</td> <td>Roof</td> <td>Good</td>	96	Roof	Good	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td></th>	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	✓ <td>97</td> <td>Bonnet</td> <td>Good</td>	97	Bonnet	Good
18	Odometer	✓	Engine		50	Oil Level	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	74	Seats	Good	98	Fuel Cap	✓	
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td>99</td><td>Mud Flaps</td><th>✓</th></th>	52	Performance	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	75	Carpets	Good	99	Mud Flaps	✓
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>76</td><td>Panels</td><td>Good</td><td>100</td><td>WOF</td><th>✓</th></th>	54	Starter Motor	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>100</td> <td>WOF</td> <th>✓</th>	76	Panels	Good	100	WOF	✓
21	Wipers Front/Rear	✓							77	Dashboard	Good			
22	Window Opener FL	✓												
23	Window Opener FR	✓												
24	Window Opener RL	✓												
25	Window Opener RR	✓												
26	Rear View Mirrors	✓												
27	Radio (Basic Test Only)	✓												
28	CD (Basic Test Only)	✓												
29	Boot Open Switch	✓												

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

#### Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Brad Lucas	Date:	06 Apr 2022
---------------	------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--