Turners


Basic Vehicle Condition Guide

Report ID: 22,225,398
Version: 1
Created: 17 May 2022

Make:	Foton	**Model:**	Tunland	**Body Style:**	Utility
Year:	2016	**Registration:**	JRP848	**Reg Expiry:**	19 Apr 2022
WoF Expiry:	28 Jan 2023	**Odometer:**	100,243 Kms	**Good No:**	22225398
VIN:	LVAV2MBB3FJ051153	**Next Service:**	102500	**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chips front window screen

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

Interior Comments

Seats	Good
Carpets	Good
Panels	scratches
Dashboard	Good

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch	✔		
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	7.1 mm		
Right front	8 mm		
Left rear	9 mm		
Right rear	8.1 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Melissa Wilson Date: 17 May 2022

I have read and understood this condition guide. Name: ..... Signature: .....