

Basic Vehicle Condition Guide

Report ID: 22,763,677


Version: 3

Created: 23 Apr 2024

Make: Model: Mazda Axela **Body Style:** Sedan Year: 2017 Registration: PKU721 Reg Expiry: 19 Feb 2025 WoF Expiry: **Odometer:** 22 Apr 2025 157,574 Kms **Good No:** 22763677 VIN: 7AT0C13JX22402771 Next Service: 166,332 Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments
RR door monsoon shield is broken

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Blair Robertson Date: 16 Apr 2024

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	v v				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	\(\times \)				
Radiator / Hoses (visual)	~				
Transmission					
Operation	V V				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes		1			
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread	depth	of tyre	es)		
Left front	5.	.0	mm		
Right front	5.5		mm		
Left rear	6.5		mm		
Right rear	6.	.5	mm		
Spare		N/A			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers 🗸					
Air Conditioning / Heater					
Operation 🗸					
Electrical / Accessories					
Head lights	<i>V</i>				
Tail lights	•				
Indicators	•				
Dashboard warning lights	-				
Wipers (front & rear) Window winder FL	,				
Window winder FR					
Window winder RL	./				
Window winder RR	<i>'</i>				
Rear view mirrors	<i>y</i>				
Radio (basic test only)	V V V V V V V V V V V V V V V V V V V				
CD (basic test only)	~				
Number of keys	1				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera			~		
		1			

I have read and understood this condition guide.

Name:

Signature: