

 Report ID:
 22,845,234

 Version:
 2

 Created:
 26 Apr 2024

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback			Pass	Fail	N/A	
Year:	2016	Registration:	KQS685	Reg Expiry:	19 Sep 2024		Engine				
WoF Expiry:	02 Mar 2024	Odometer:	62,458 Kms	Good No:	22845234		Oil level			~	
VIN:	SJNFAAZE0U6058389	Next Service:	69,000	Service Histor	y: Yes		Smoke & fumes	~			
							Performance	V			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic te	sting undertaken. The	vehicle has beei	n driven up to 50km/h	from cold. The	Vendor recomme	nds	Cooling System			1	
a full mechan	nical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.		Coolant condition	~		1	
	S D		S S		S	٦	Performance	r		1	
Key:				-01-		-	Radiator / Hoses (visual)	r		<u> </u>	
S = scratch D = dent	TE				Tan		Transmission	1		1	
B = rust	s sc			710	HILLS		Operation	~		1	
PT = paint defe	ect NP	IT I			101h		Noise	~		1	
C = crack					S R SC		Clutch			~	
P = pin dent	SRSC DE				74116	25	CV joints	~			
* = decals		10		To .	ED S	1	Wheel bearings	~			
SC = stone chips W = significant scuffs							Brakes				
	S		S S		S		Performance	~		Τ	
Body Incr	pection Comments	Note: sor	ne defects & blemishes	s may not be dis	played in the diagr	am	Hand Brake	~		1	
Space saver supplied aftermarket, removed and stashed aside. Rh parcel tray pin broken							Tyres (lowest observed tread depth of tyres)				
			F				Left front	4	.0	mm	
							Right front	4	.0	mm	
							Left rear	3	.0	mm	
Conditio	ns During Body Ins	pection:	Dry				Right rear	5	.0	mm	
							Spare	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments							Suspension	•			
Tested 12v	battery and passed. Vel	hicle has belly pa	ans				Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater	•			
							Operation	~			
Interior Comments							Electrical / Accessories				
Seats	Good						Head lights	~			
Comoto	Good					-	Tail lights	~			
Carpets						_	Indicators	~			
Panels	scuffs scra	tches marks					Dashboard warning lights	~			
	Good					-	Wipers (front & rear)	~			
Dashboa	iru						Window winder FL	~			
	_						Window winder FR	~			
General C	<u>Comments</u>						Window winder RL	~			
							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
							Number of keys	2			
Road Conditions During Test Drive: Dry							Central locking	~			
							Remote locking	~			
Engine Timing Mechanism: Unknown							Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement:	Not Applicable	Kms:			Reversing camera	~			
Inspected by: Gary Adams Date: 13 Nov 2023											
Inspected by: Gary Adams Date: 13 Nov 2023											

I have read and understood this condition guide.

Name:

Signature: