

## **Basic Vehicle Condition Guide**

Report ID: 22,858,734


Version: 2

Created: 15 Aug 2023

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2011 Registration: GDY58 **Reg Expiry:** 13 Dec 2023 WoF Expiry: **Odometer:** 25 Feb 2024 259,444 Kms **Good No:** 22858734 VIN: MR0FZ22GX01058795 Next Service: 268500 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Rust around windscreen Stone chips on windscreen

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Minor surface rust

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

## **General Comments**

Drives well. Service records provided by the lease company: 163175 KM 165,000 KM SERVICE EBBETT TOYOTA HAMILTON (MAINT) 174453 KM 170,000 KM SERVICE EBBETT TOYOTA HAMILTON (MAINT) 184999 KM 180,000 KM SERVICE EBBETT TOYOTA HAMILTON (MAINT) 212199 KM 210,000 KM SERVICE EBBETT TOYOTA HAMILTON (MAINT)

227382 KM 225,000 KM SERVICE EBBETT TOYOTA HAMILTON (MAINT)

241705 KM 240,000KM SERVICE EBBETT TOYOTA HAMILTON (MAINT)

Engine Timing Mechanism: Cambelt

Road Conditions During Test Drive:

**Evidence of Cam Belt Replacement:** Kms: 149,474 Yes

Dry

31 Jul 2023 Inspected by: Jaykib Collins Date:

Name: .....

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	V V			
Radiator / Hoses (visual)	~			
Transmission	•			
Operation	~			
Noise	\( \times \)			
Clutch	~			
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	3	.0	mm	
Right front	4	.0	mm	
Left rear	2	.0	mm	
Right rear	2.0		mm	
Spare		Yes		
Suspension				
Suspension performance	>			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	V V V V V V V V V V V V V V V V V V V			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			~	

Signature: .....