

Report ID: 22,905,468 2 Version: 14 Apr 2025 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A	
Year:	2019	Registration:	LZR936	Reg Expiry:	27 May 2025	Engine			,	
WoF Expiry:		Odometer:	170,895 Kms	Good No:	22905468	Oil level	~			
VIN:	MPATFS85JJG000199	Next Service:	-	Service Histor		Smoke & fumes	~			
					,	Performance	~			
	port is not a warranty		~ · · ·			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	DSC	-0				Radiator / Hoses (visual)	~			
S = scratch						· · ·	Transmission			
D=dent SW 66							Operation 🖌			
R = rust				10	JHH	Noise	~			
PT = paint def C = crack	ect M			+	P SC	Clutch	~			
P = pin dent	Ho	KI			JUII —	CV joints	~			
* = decals SSC PIP						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance				
		Noto: con	he defects & blemishes		layed in the diagram	Hand Brake	~			
Body Insp	pection Comments	Note. son	le délects & biennisnes	may not be disp	layed in the diagram					
Both lower side sills dented						Tyres (lowest observed tread depth of tyres)				
Glue residue on front left door						Left front	-	.0	mm	
Right rear tail light isn't working Front left bar/bumper trim is damaged						Right front			mm	
						Left rear			mm	
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
Engine cover broken						Suspension				
						Suspension performance	~			
						Steering performance	~			
	Shock absorbers	~								
						Air Conditioning / Heater			1	
						Operation	~			
						Electrical / Accessories			1	
Seats	Stains on f	ront seats, large	rip on drivers seat			Head lights	~			
Carpets	Average					Tail lights		~		
						Indicators	~			
Panels	Average					Dashboard warning lights		~		
Dashboa	rd Screw bol	es in dashboard				Wipers (front & rear)	~			
						Window winder FL	~			
Concret						Window winder FR	~			
<u>General Comments</u>						Window winder RL			~	
-	ning light on					Window winder RR			~	
kadio scree	n delaminating					Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	3	1		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~			
Engine T:	ming Machanian	T:	Cho:n			Remote locking	~			
-	ming Mechanism:	Timing (K.		Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Increate	Inspected by: Hoani Saunders Date: 14 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: