

Report ID: 22,916,018 Version: 1 30 Apr 2024 Created:

Make:	Opel	Model:	Combo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2021	Registration:	QGM225	Reg Expiry:	13 Nov 2024	Engine			
WoF Expiry:	15 Dec 2024	Odometer:	4,377 Kms	Good No:	22916018	Oil level	~		
VIN:	W0VECYHZRNJ508062	Next Service:	15000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Dauta hava nat	hoon diamonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	LS			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	SC DI			215	HIV	Operation	~		
PT = paint defe		F I		$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	sc 916			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant			P			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	6.0	)	mm
						Right front	7.0	)	mm
						Left rear	6.0	)	mm
Conditions During Body Inspection: Dry						Right rear	7.0	7.0 mm	
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	_					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashhar	Good					Wipers (front & rear)	~		
Dashboa	iru					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
•						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive:   Dry   Central locking							~		
	ming Masheritan	11				Remote locking	~		
Engine Timing Mechanism: Unknown   Evidence of Cam Belt Replacement: Not Applicable Kms:   Beversing camera									~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Chris Buckley Date: 30 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....