

 Report ID:
 22,916,952

 Version:
 2

 Created:
 05 Mar 2024

| Make: | Subaru | Model: | XV | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|---|------------------|------------------------|-------------------|-----------------------|--|--------|------|-----|
| Year: | 2013 | Registration: | NRJ206 | Reg Expiry: | 02 May 2024 | Engine | • | | • |
| WoF Expiry: | 18 Mar 2025 | Odometer: | 125,375 Kms | Good No: | 22916952 | Oil level | ~ | | |
| VIN: | 7AT0GF1XX21004954 | Next Service: | 135000 | Service Histor | r y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a run mechan | lical inspection phor to | i purchase and t | nis can be arranged ic | | charge. | Coolant condition | ~ | | |
| | SC W | | D SC | | | Performance | ~ | | |
| Key: S = scratch | | \sim (0) | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| | | | | | | Transmission | | | |
| R = rust | S D SC | | | 10 | Ell Is | Operation | ~ | | |
| PT = paint def | ect NP | 1 | | | | Noise | ~ | | |
| C = crack | | | | TT | SC | Clutch | | | ~ |
| P = pin dent | PSC DE | | | | 24Ub | CV joints | ~ | | |
| * = decals | | 10 | | 10 | ED SP | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| | | C | D | | | Performance | ~ | | |
| Body Inst | pection Comments | Note: sor | ne defects & blemishes | s may not be disp | played in the diagram | Hand Brake | ~ | | |
| L/R Taillight Cracked, | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 5.0 | | mm |
| | | | | | | Right front | 6 | .0 | mm |
| | | | | | | Left rear | 2 | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3.0 mm | | |
| | | | | | | Spare | N/A | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | _ | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpote | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| · | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | 1 | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | ~ | | |
| Inspecter | Inspected by: Chris Buckley Date: 19 Feb 2024 | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature:

.