

Report ID: 22,917,329 Version: 1 09 Feb 2024 Created:

| Make: | Mitsubishi | Model: | Outlander | Body Style: | SUV | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|--------------------|----------------------|--|--------|--------|-----|
| Year: | 2020 | Registration: | NBZ876 | Reg Expiry: | 12 Oct 2024 | Engine | - | | L |
| WoF Expiry: | 13 Oct 2024 | Odometer: | 104,769 Kms | Good No: | 22917329 | Oil level | ~ | | |
| VIN: | JMFXDGG3WLZ00113 | Next Service: | 109000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tl | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | sc | -0 | SC P SC | -161- | sc | Radiator / Hoses (visual) | · · | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | s sc | | | TIN | FILL S | Operation | ~ | | |
| R = rust PT = paint defe | | | | \prod | | Noise | · · | | |
| C = crack | | | | + | SC | Clutch | | | ~ |
| P = pin dent | | | | | ᅰЦ | CV joints | ~ | | |
| * = decals | sc 916 | | | | ELIPS- | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs SC W P P P S | | | | | | Performance | ~ | | |
| | | Note: son | ne defects & blemishes | may not be disr | | Hand Brake | ~ | | |
| Body Insp | pection Comments | 10000.3011 | le delects à blemistie | indy not be disp | hayed in the diagram | | | ofturo | (|
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 7. | | mm |
| | | | | | | Right front | 7. | | mm |
| | | | | | | Left rear | 3. | | mm |
| Conditions During Body Inspection: Dry | | | | | | - | | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare N/A | | | |
| | inage & onder bor | mermspectic | <u>on comments</u> | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpote | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ru | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| · | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | • | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| | | | | | | | 1 | | |
| Inspected by: Chris Buckley Date: 08 Feb 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: