

•	Report ID:	22,925,480	Version:	2
	Created:	14 Nov 2025		


	ОК	Requires Attention	
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	1		
Noise	~		
Coolant condition	~		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	~		
Noise	/		
Clutch			/
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	•		
Hand brake	•		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		6	6.0 mm
Right front		6	3.0 mm
Left rear		6	3.0 mm
Right rear		6	6.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		1	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	•		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	/		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors	•		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2	1	
Central locking	•		
Remote locking	•		
Sat. nav. (basic test only)	/		
Reversing camera			

Make:	Mazda	Model:	CX-9
Body Style:	SUV	Year:	2022
Rego No.:	RJU413	Rego Expiry:	26 Mar 2026
WoF Expiry:	24 Sep 2026	Odometer:	83,476 Kms
Good No.:	22925480	VIN:	JM0TC4WLA00557028
Next Service:	90,000 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ĸey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Requires remote batteries

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	

I have read and	understood
this condition of	uide.

Inspection Date: 30 Oct 2025

NAME			

SI	GN	AT	URF	