•	Report ID:	22,925,825	Version:	3	
	Created:	13 Nov 2025			

OK

1 1 Requires Attention

N/A

OT.		Pagi	c Condition Guide	Report ID: 22,92	25,8
	urner	S	C Condition Guide	Created: 13 No	ov 2
Make:	Audi	Model:	Q4 E-Tron		
Body Style:	SUV	Year:	2023	Engine	
Rego No.:	RLD3	Rego Expiry:	02 Aug 2026	Oil level	
WoF Expiry:	27 Jul 2026	Odometer:	29,897 Kms		
Good No.:	22925825	VIN:	WAUZZZFZ8PP054717	Smoke & fumes	
Next Service:	32,000 Kms	Service History:	Yes	Engine performance	
Note: This report is	not a warranty	,		Noise	
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or n from cold. The Vendor recommends a	Coolant condition	
full mechanical inspe	ection prior to purchase an	d this can be arranged f	or an additional charge.	Cooling performa	
Key				Radiator / Hoses (v	/isua
•	= Rust $C = C$	rack *= Deca	ls W = Significant scuffs	Transmission	
D = Dent P1	$\Gamma = Paint defect P = Paint defect$	in dent SC = Sto	ne Chips	Operation	
	Noise				
	Clutch				
	(A)			CV joints	
				Wheel bearings	
S SC				Brakes	
				Performance	
				Hand brake	
	18			Tyres (lowest obse	erve
				Left front	
			(Q)	Right front	
	\angle			Left rear	
][Right rear	

Note: some defects and	l blamichae may not	ha dicalayad in	tha diaaram
Note, some defects and	i bieillishes may not	De displayed III	tile diadiaili

Body Inspection Comments

Tire inflation kit in boot

Conditions During Body Inspection	Dry					
Under Carriage and Under Bonnet Inspection Comments						

Interior Comm	ents
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Air conditioning and heating systems along with reverse camera and navigation working at time of inspection.

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Unknown		
Evidence of Can	n Belt Replacement	Yes	No	Kms
Inspected by:	Gary Adams			
Published by:	Published by: Amanda Loader			
Inspection Date:	Inspection Date: 10 Oct 2025			

Cooling performance				
Radiator / Hoses (visual)	'			
Transmission				
Operation	1			
Noise	/			
Clutch			,	_
CV joints	/			
Wheel bearings	/			
Brakes				
Performance	/			
Hand brake	/			
Tyres (lowest observed tread d	lepth of	tyres)		
Left front			5.0 r	nm
Right front		5	5.0 r	nm
Left rear		4	1.0 r	nm
Right rear		4	1.0 r	nm
Spare	N/A			
Suspension				
Suspension performance	1			
Steering performance	<i>'</i>			
Shock absorbers	1			
Air Conditioning / Heater				
Operation	1			
Electrical / Accessories				
Head lights	1			
Tail lights	1			
Indicators	1			
Dashboard warning lights	/			
Wipers (front & rear)	1			
Window winder FL	~			
Window winder FR	1			
Window winder RL	1			
Window winder RR	1			
Rear view mirrors	1			
Radio (basic test only)	1			
CD (basic test only)			~	
Number of keys	2			
Central locking	1			
Remote locking	/			
Sat. nav. (basic test only)	1			
Reversing camera	1			
SIGNATURE				

П	ha	ve	rea	d a	n	b	un	de	rs	to	od
tł	nis	CO	nd	itio	n	gı	uic	le:			