

| | | | |
|------------|-------------|----------|---|
| Report ID: | 22,927,921 | Version: | 7 |
| Created: | 12 Dec 2025 | | |


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Ford | Model: | Puma |
| Body Style: | SUV | Year: | 2023 |
| Rego No.: | QHF81 | Rego Expiry: | 20 Dec 2025 |
| WoF Expiry: | 11 Dec 2026 | Odometer: | 59,247 Kms |
| Good No.: | 22927921 | VIN: | WF02XXERK2PT78590 |
| Next Service: | 74,000kms | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Wet

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

| | |
|------------|---------|
| Seats: | Average |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Average |

General Comments

Air conditioning and heating systems, along with reverse camera and navigation working at time of inspection.

| | |
|-----------------------------------|---|
| Road Conditions During Test Drive | Dry |
| Engine Timing Mechanism | Timing Chain |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes <input type="checkbox"/> No Kms |
| Inspected by: | Gary Adams |
| Published by: | Anna Zandstra |
| Inspection Date: | 29 Jul 2025 |

OK Requires Attention N/A

Engine

| | | | |
|---------------------------|---|--|--|
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |

Transmission

| | | | |
|----------------|---|--|---|
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |

Brakes

| | | | |
|-------------|---|--|--|
| Performance | ✓ | | |
| Hand brake | ✓ | | |

Tyres (lowest observed tread depth of tyres)

| | |
|-------------|--------|
| Left front | 7.0 mm |
| Right front | 7.0 mm |
| Left rear | 4.0 mm |
| Right rear | 5.0 mm |
| Spare | Yes |

Suspension

| | | | |
|------------------------|---|--|--|
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |

Air Conditioning / Heater

| | | | |
|-----------|---|--|--|
| Operation | ✓ | | |
|-----------|---|--|--|

Electrical / Accessories

| | | | |
|-----------------------------|---|--|---|
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | ✓ | | |
| Reversing camera | ✓ | | |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____