

Report ID:	22,933,963
Version:	3
Created:	28 Mar 2024

Make:	Dodge	Model:	Challenger	Body Style:	Sedan			Pass	Fail	N/A	
Year:	2017	<b>Registration:</b>	PWZ420	Reg Expiry:	23 May 2024	E	ngine			-	
WoF Expiry:	07 Nov 2024	Odometer:	46,002 Kms	Good No:	22933963		Oil level	~			
VIN:	2C3CDZFJ7GH289569	Next Service:	53,000	Service History	<b>y:</b> Yes	⅃∟	Smoke & fumes	~			
Noto: This ro	nort is not a warranty					٦L	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic te	sting undertaken. The ical inspection prior to	vehicle has beer	n driven up to 50km/h	۱ from cold. The ۱	lendor recommends		Cooling System				
a fuil mechan	lical inspection phor to	purchase and t	his can be arranged ic		narge.	ןו	Coolant condition	~			
	S		S S		S	٦٢	Performance	~			
Key:		= $(0)$		5(0)-			Radiator / Hoses (visual)	~			
S = scratch D = dent	TE				A	ı T	ransmission				
R = rust	s sc			210	S SC	1	Operation	~			
PT = paint def	ect NP				101h	١Ŀ	Noise	~			
C = crack					S		Clutch			~	
P = pin dent	HE			$\langle \rangle$	74JUL		CV joints			~	
* = decals	s sc gle			TO	FID SSC	]	Wheel bearings	~			
SC = stone chips						Brakes					
W = significant scuffs S S S S S						Performance	~				
Bodylas	pection Commonts	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram		Hand Brake	~			
1 .	pection Comments	1					yres (lowest observed tread		of tyre	≥s)	
Front bumper under panel loose. No spare tire supplied by manufacturer. Stone chips in front screen.						Left front	. 4.	.0	mm		
							Right front	5.	.0	mm	
						╧	Left rear	8.		mm	
Condition	os During Body Ins	nection:	Dry			٦ŀ	Right rear	8.		mm	
	Conditions During Body Inspection: Dry					┛┝	Spare N/A				
Under Carriage & Under Bonnet Inspection Comments					s	Suspension					
Tested batt	ery and passed. Runs of	n 95/98 octane fi	uel				Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater	·			
						Ţŀ	Operation 9	~			
Interior C	<u>comments</u>						lectrical / Accessories	·			
Seats Good					IF	Head lights					
							Tail lights	~			
Carpets	Good						Indicators	~			
Panels	Good						Dashboard warning lights	~			
							Wipers (front & rear)	~			
Dashboa	ard Good						Window winder FL	~			
						┛┠	Window winder FR	~			
General C	Comments					7ŀ	Window winder RL	•		~	
Air conditioning is working fine at inspection. Only one remote control is working. Navigational system					Window winder RE			<i>v</i> <i>v</i>			
doesn't appear to work						Rear view mirrors	~		<b>•</b>		
							Radio (basic test only) CD (basic test only)	~			
							Number of keys	2		~	
					╡┝	•	2				
Road Con	ditions During Tes	t Drive:	Dry			┨┝	Central locking	<ul> <li></li> <li></li> </ul>		<u> </u>	
Engine Ti	ming Mechanism:	Timing	Chain			┓┝	Remote locking	~			
•	of Cam Belt Replac	-	lot Applicable	Kms:			Sat. Nav. (basic test only)			~	
		richichi I					Reversing camera	~			
Inspected by: Gary Adams Date: 19 Dec 2023											

I have read and understood this condition guide.

Name: .....