Turners

Basic Vehicle Condition Guide

Report ID: 22,950,648
Version: 1
Created: 29 Feb 2024

Make:	Ford	**Model:**	Ranger	**Body Style:**	Utility
Year:	2013	**Registration:**	PAA842	**Reg Expiry:**	30 Nov 2023
WoF Expiry:	13 Jul 2024	**Odometer:**	302,498 Kms	**Good No:**	22950648
VIN:	MNAUMFF50CW1585	**Next Service:**	291,145kms	**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Lower grille in front bumper is broken & part of it is missing. Large dent in left rear bumper & very large dent in right side of rear deck. Lens missing off indicator repeater on right side wing mirror. Small stone crack in right side (cva) area of windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments

Seats	Average
Carpets	Average
Panels	Poor
Dashboard	Poor

General Comments

Screw holes in centre console. Sunglasses storage pocket in front head lining will not stay closed. Interior of ute is very dirty. Power socket in right side of centre dash trim is missing. Clip broken on plastic panel on side of left front seat. Right front headlight is not working on low beam.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints			✔
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	10.0 mm		
Right front	10.0 mm		
Left rear	2.8 mm		
Right rear	2.8 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights		✔	
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR		✔	
Window winder RL		✔	
Window winder RR		✔	
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	1		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Jason Young Date: 29 Feb 2024

I have read and understood this condition guide. Name: ..... Signature: .....