


<b>Make:</b>	Hyundai	<b>Model:</b>	I30	<b>Body Style:</b>	Wagon
<b>Year:</b>	2011	<b>Registration:</b>	GDC512	<b>Reg Expiry:</b>	25 Oct 2024
<b>WoF Expiry:</b>		<b>Odometer:</b>	236,634 Kms	<b>Good No:</b>	22955415
<b>VIN:</b>	KMHDC81SMCU13514	<b>Next Service:</b>	243,000kms	<b>Service History:</b>	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Small stone crack in left side of windscreen. Dents in right & left side sills, one under drivers door & one under left front door.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Oil weeping from right output shaft seal on gearbox.

**Interior Comments**

Seats	Average
Carpets	Good
Panels	Average
Dashboard	Average

**General Comments**

\*\* Car is on a COF not a WOF\*\*

Hole worn in fabric on backrest of drivers seat. Sun glasses pocket in front interior roof lining is broken off, is sitting in glovebox. Steering wheel covering is worn.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	4.4	mm	
Right front	4.2	mm	
Left rear	5.0	mm	
Right rear	6.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 26 Mar 2024

I have read and understood this condition guide.

Name: .....

Signature: .....