

Basic Condition Guide

Report ID:	23,046,941	Version:	1
Created:	11 Nov 2025		

U	nuer	S Basi	C Condition Guide	Created:	11 Nov 2025					
Make: Subaru		Model:	Forester				Requires			
Body Style:	suv	Year:	2022	Engine		OK	Attention	N/A		
Rego No.:	PPT95	Rego Expiry:	22 Nov 2026			V				
WoF Expiry:	12 Nov 2026	Odometer:	91,710 Kms	Oil level		<i>'</i>				
Good No.: 23046941		VIN:	JF2SK9KL5PG091140	Smoke & fumes		<i>'</i>				
Next Service:	103,000	Service History:	No	Engine performance		<i>'</i>				
Note: This report is r	not a warranty	Noise Coolant co		<i>'</i>						
This report is a guide	only. Consideration is mad									
diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					rformance	<i>'</i>				
Key		Radiator / Hoses (visual)								
	= Rust $C = C$	Transmission								
D = Dent PT	= Paint defect $P = Pi$	Operation		/						
SC		sc sc		Noise		•				
				Clutch						
				CV joints		/				
sc w				Wheel bea	rings	/				
W Al				Brakes						
\mathcal{H}	M = 11	N	SC	Performan	ce	~				
1 1				Hand brake	2	'				
sc	M - I			Tyres (lowest observed tread depth of tyres)						
J				Left front			6	5.5 mm		
				Right front			6	6.5 mm		
-				Left rear		6.5 mm				
SC		sc sc		Right rear		6.5 mm				
Note: some defects a	and blemishes may not be	displayed in the diagra	ım	Spare Yes						
Body Inspection	on Comments			Suspensio	n					
				Suspension	performance	1				
				Steering pe	erformance	V				
				Shock abso	orbers	/				
Conditions Duri	ng Body Inspection		Dry	Air Conditioning / Heater						
Under Carriage	e and Under Bonnet	Inspection Comm	ents	Operation		~				
					Electrical / Accessories					
				Head lights	5	1				
				Tail lights		V				
Interior Comm	ents			Indicators		1				
Seats:	Good			Dashboard	warning lights	•				
Carpets:	Good		Wipers (fro	nt & rear)	•					
Panels: Good					inder FL	•				
Dashboard: Good					inder FR	1				
General Comm	nents		Window w	inder RL	1					
				Window w	inder RR	1				
				Rear view r	nirrors	1				
				Radio (basi		1				
Road Condition	s During Test Drive	Dry	 	CD (basic to	· · · · · · · · · · · · · · · · · · ·			✓		
Engine Timing I		 	Number of		2					
Engine Timing Mechanism Unknown Evidence of Cam Belt Replacement Yes No Kms				Central loc		1				
	Tyler Le Bherz			Remote loc		<i>'</i>				
mspected by.	. , 101 -0 -011612			nemote iot	19	_				

I have read and understood this condition guide:

Tyler Le Bherz

11 Nov 2025

Published by:

Inspection Date:

NAME

Sat. nav. (basic test only)

Reversing camera