

Report ID: 23,076,805

Version:


19 Mar 2024 Created:

Fail

N/A

mm

 mm mm $\mathsf{m}\mathsf{m}$



Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Daryll Timms

I have read and understood this condition guide.

Inspected by:

| | ' | | | | | | | | | |
|------------------|-----------------------------|---|---|--|--|--|--|--|--|--|
| | Sat. Nav. (basic test only) | | ~ | | | | | | | |
| Kms: | Reversing camera | ~ | | | | | | | | |
| Name: Signature: | | | | | | | | | | |

CD (basic test only) Number of keys

Central locking

3

| Make: | Toyota | Model: | Hiace | Body Style: | Van | | Pass | Fail | [|
|---|--|------------------|-------------------|------------------------------|--|---------------------------|----------|------|-----|
| Year: | 2016 | Registration: | JRG85 | Reg Expiry: | 14 Mar 2025 | Engine | | • | |
| WoF Expiry: | 22 Feb 2025 | Odometer: | 71,075 Kms | Good No: | 23076805 | Oil level | ~ | | |
| VIN: | JTFPT22P400016995 | Next Service: | 80,000kms | Service Histor | r y: Yes | Smoke & fumes | ~ | | |
| Nata This as | | | | | | Performance | ~ | | |
| | port is not a warranty a guide only. Conside | | for age and mile | eage. Parts have not | : been dismantled or | Noise | ~ | | |
| diagnostic te | sting undertaken. The nical inspection prior to | vehicle has beer | driven up to 50 | km/h from cold. The | Vendor recommends | Cooling System | | • | |
| a ruii iiieciiai | ilcai irispection prior to | purchase and the | iis can be arrang | ed for all additional c | charge. | Coolant condition | ~ | | |
| | SC | | S | | | Performance | ~ | | |
| Key: | | $=$ (\circ) | | $\equiv \langle O \rangle =$ | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | Transmission | | | | |
| R = rust | | 1 | | | SD | Operation | ~ | | |
| PT = paint def | ect NP | | | | 11111 | Noise | ~ | | |
| C = crack | | | | | S D SC | Clutch | | | ļ |
| P = pin dent | PSC | | | | 711116 | CV joints | | | Ī |
| * = decals | | | | | S D SC | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | ~ | Brakes | | | | |
| w – signincan | SC S | | SC D: | sc s | P SC | Performance | V | | |
| Rody Insi | oection Comments | Note: son | ne defects & blem | nishes may not be disp | played in the diagram | Hand Brake | ~ | | Г |
| Grille scratched. Cracked & chipped windscreen, replacement needed. | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| Tow hook o | covers missing. | | | | | Left front | 7 | 7 | m |
| L/H tail ligh Rear wiper | it cracked. blade missing. | | | | | Right front | { | 8 | m |
| | | | | | | Left rear | ï | 5 | m |
| Conditio | ns During Body Ins | pection: | Dry | | | Right rear | { | 8 | m |
| | <u> </u> | | | | | Spare | | Yes | _ |
| <u>Under Ca</u> | ırriage & Under Bor | nnet Inspectio | on Comments | | | Suspension | | | _ |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | Г |
| | | | | | | Shock absorbers | ~ | | Г |
| | | | | | | Air Conditioning / Heater | | ļ | |
| | | | | | | Operation | V | | Γ |
| Interior C | <u>Comments</u> | | | | | Electrical / Accessories | | | _ |
| Seats | Average | | | | | Head lights | ' | | Γ |
| | Average | | | | | Tail lights | ~ | | T |
| Carpets | , werage | | | | | Indicators | ~ | | T |
| Panels | R/R windo | w catch broken. | | | | Dashboard warning lights | ~ | | T |
| | Average | | | | | Wipers (front & rear) | ~ | | r |
| Dashboa | ard Average | | | | | Window winder FL | ~ | | T |
| | ' | | | | | Window winder FR | ~ | | |
| | <u>Comments</u> | | | | | Window winder RL | | | T . |
| 11 seater high roof minibus, 2 seats front, 9 rear. | | Window winder RR | | | Ι, | | | | |
| | | | | | | Rear view mirrors | ~ | | T |
| | | | | | | Radio (basic test only) | ~ | | T |