

Report ID: 23,077,936 Version: 2 04 Mar 2024 Created:

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2019	Registration:	MGU331	Reg Expiry:	22 Jul 2024	Engine		-	
WoF Expiry:		Odometer:	122,059 Kms	Good No:	23077936	Oil level	~		
VIN:	TMAJ281ASKJ880235	Next Service:		Service Histor		Smoke & fumes	~		
			,			Performance	~		
	port is not a warranty		~ · · ·			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	SC	-0	s sc s sc		SC	Radiator / Hoses (visual)	~		
S = scratch	Se	10			X	Transmission	V		
D = dent				The	S D SC	Operation	~		<u> </u>
R = rust				10		Noise	~		
PT = paint def C = crack	ect			+	PT SC	Clutch	~		
P = pin dent	Htc	KI			JUII —				~
* = decals	sc pp					CV joints	~		
SC = stone chi	ps US	LA		10		Wheel bearings	~		
W = significant scuffs SC P SC						Brakes	. <i> </i>		<u> </u>
		Notes as				Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Minor dents and scratches right inner wheel arch Right front sill step plate worn and minor dents						Tyres (lowest observed tread depth of tyres)			
Right front	sill step plate worn and	minordents				Left front	7.	-	mm
						Right front	7.		mm
						Left rear	4.		mm
Conditions During Body Inspection: Dry						Right rear	510		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage & onder bor	metmspectic	<u>on comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	scratches	cargo area trim				Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
F. • =						Remote locking	~		
-	ming Mechanism:	Timing				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Dean Sinclair Date: 04 Mar 2024									

I have read and understood this condition guide.

Name:

Signature: