



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID: 23,795,139

Version: 2

Created: 08 Apr 2024

Make:	Subaru	Body Style:	Wagon
Model:	Impreza	VIN:	7AT0GF09X23008432
Year:	2017	Odometer:	111,008 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•					
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good						
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	8.0	mm	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>8.0</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>8.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	62	Right Front	8.0	mm	63	Left Rear	8.0	mm	85	R/H Mirror	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>64</td> <td>Right Rear</td> <td>8.0</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>N/A</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	8.0	mm	65	Spare	N/A	86	L/H Mirror	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	66	Tools	✓	87	L/F Guard	Good	88	R/F Guard	Good			
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	89	L/H Doors	Good	90	R/H Doors	Good	
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td><td>92</td><td>R/H Sill</td><td>Good</td></th>	69	Seatbelts	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	91	L/H Sill	Good	92	R/H Sill	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	71	Seat Heaters	•	93	Boot/Tail Gate	Good	94	Front Bumper	Good
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	95	Rear Bumper	Good	96	Roof	Good
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	74	Seats	Good	75	Carpets	Good	97	Bonnet	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th>	46	Handbrake	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	76	Panels	Good	77	Dashboard	Good	98	Fuel Cap	✓
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>48</td> <td>Remote Locking</td> <th>✓<td>49</td><td>Number of Keys</td><td>1</td><td>99</td><td>Mud Flaps</td><th>✓</th></th>	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	49	Number of Keys	1	99	Mud Flaps	✓	
17	Speedo	✓	Engine		50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td>100</td><td>WOF</td><th>✓</th></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	52	Performance	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓	
18	Odometer	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓</th>	54	Starter Motor	✓									
19	Rev Counter	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
20	Fuel Gauge	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
21	Wipers Front/Rear	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
22	Window Opener FL	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
23	Window Opener FR	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
24	Window Opener RL	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
25	Window Opener RR	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
26	Rear View Mirrors	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
27	Radio (Basic Test Only)	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
28	CD (Basic Test Only)	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															
29	Boot Open Switch	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>															

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Lewis Dolamore	Date:	10 Aug 2023
I have read and understood this condition guide:			
Name:		Signature:	