



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	23,875,867
Version:	1
Created:	27 Sep 2023

Make:	Toyota	Body Style:	Hatchback
Model:	Vitz	VIN:	7AT0H63EX23133420
Year:	2014	Odometer:	53,071 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•					
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>7.0</td><td>mm</td><td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>61</td> <td>Left Front</td> <td>7.0</td> <td>mm</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	61	Left Front	7.0	mm	83	Front Wiper Blades	Good		
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	7.0	mm	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>63</td> <td>Left Rear</td> <td>7.0</td> <td>mm</td> <td>64</td> <td>Right Rear</td> <td>7.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	63	Left Rear	7.0	mm	64	Right Rear	7.0	mm	85	R/H Mirror	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>65</td> <td>Spare</td> <td>N/A</td> <td>66</td> <td>Tools</td> <th>✓</th> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	65	Spare	N/A	66	Tools	✓	86	L/H Mirror	Good			
9	Reversing Lights	✓	39	Wheel Balance	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓</th> <td>68</td> <td>Heater Fan</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td>	Interior		67	AC Operation	✓	68	Heater Fan	✓	87	L/F Guard	Good	
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•	88	R/F Guard	Good
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	89	L/H Doors	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	90	R/H Doors	Good
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		79	Fuel Flap Release	✓	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	91	L/H Sill	Good
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td> <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>85</td><td>R/H Mirror</td><td>Good</td><td>86</td><td>L/H Mirror</td><td>Good</td><td>87</td><td>L/F Guard</td><td>Good</td></th>	46	Handbrake	✓ <td>85</td> <td>R/H Mirror</td> <td>Good</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td> <td>89</td> <td>L/H Doors</td> <td>Good</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>91</td> <td>L/H Sill</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	49	Number of Keys	1	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good
18	Odometer	✓	Engine		50	Oil Level	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th><td>99</td><td>Mud Flaps</td><th>✓</th></th>	52	Performance	✓ <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	54	Starter Motor	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓						
21	Wipers Front/Rear	✓															
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✓															
29	Boot Open Switch	✓															

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	27 Sep 2023
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--