

Report ID: 23,911,998 Version: 1 09 Feb 2024 Created:

Make:	Honda	Model:	Vezel	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:	QCK459	<b>Reg Expiry:</b>	23 Aug 2024	Engine			L
WoF Expiry:	06 Nov 2024	Odometer:	106,499 Kms	Good No:	23911998	Oil level	~		
VIN:	7AT08GDHX23225859	Next Service:	116,000 kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	LS	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S SC			715	S SC	Operation	~		
PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74114	CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			<u> </u>
W = significant			S			Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			L 2S)
						Left front	Left front 5.2		
						Right front	5.		mm
						Left rear	5.	.4	mm
Conditions During Body Inspection: Dry						Right rear	5.4 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension	·		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	onditioning / Heater		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Front seat	s average otherw	vise good			Head lights	~		
	Good					Tail lights	~		
Carpets	3000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
Remote loc							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
							24		
Inspected by: Hugh Stuart Date: 09 Feb 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....