



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,417,397
Version:	1
Created:	08 Dec 2023

Make:	Lexus	Body Style:	
Model:	CT200H	VIN:	
Year:	2011	Odometer:	83,919 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30 Fuel Flap Release		31 Reversing Camera		Cooling System		Exterior								
1	Battery	✓		✓		55	Coolant Condition	✓	78	Under Carriage	Good					
2	Headlights	✓		✓		56	Performance	✓	79	Sun Roof Operation	•					
3	Tail Lights	✓		✓		57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good					
4	High Stop Light	✓		✓		Transmission and Drive		Suspension		81	Back Windscreen (no chips)	Good				
5	Front Right Indicators	✓		✓		34	Operation	✓	58	Suspension Performance	✓					
6	Front Left Indicators	✓		✓		35	Noise	✓	59	Steering Performance	✓					
7	Rear Right Indicators	✓		✓		36	Clutch	•	60	Shock Absorbers	✓					
8	Rear Left Indicators	✓		✓		37	CV Joints	✓	Wheels and Tyres		82	Side Windows (no chips)	Good			
9	Reversing Lights	✓		✓		38	Wheel Bearing	✓	61	Left Front	6	mm	83	Front Wiper Blades	Good	
10	Rear Reflectors	✓		✓		39	Wheel Balance	✓	62	Right Front	6	mm	84	Rear Wiper Blade	Good	
11	Hazard Lights	✓		✓		40	Gearbox (Manual)	•	63	Left Rear	7	mm	85	R/H Mirror	Good	
12	Courtesy Lights	✓		✓		41	Engine Timing	Timing Chain	64	Right Rear	7	mm	86	L/H Mirror	Good	
13	Dashboard Lights	✓		✓		42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	Yes		87	L/F Guard	Good	
14	Dashboard Dimmer Switch	✓		✓		43	Replaced at (odometer reading)		66	Tools	✓		88	R/F Guard	Good	
15	Number Plate Light	✓		✓		Brakes		Interior		67	AC Operation	✓	89	L/H Doors	Good	
16	Dashboard Warning Lights	✓		✓		44	Front Brakes	✓	68	Heater Fan	✓		90	R/H Doors	Good	
17	Speedo	✓		✓		45	Rear Brakes	✓	69	Seatbelts	✓		91	L/H Sill	Good	
18	Odometer	✓		✓		46	Handbrake	✓	70	Horn	✓		92	R/H Sill	Good	
19	Rev Counter	•		✓		Keys and Locking		Interior		71	Seat Heaters	✓		93	Boot/Tail Gate	Good
20	Fuel Gauge	✓		✓		47	Central Locking	✓	72	Sun Visors	✓		94	Front Bumper	Good	
21	Wipers Front/Rear	✓		✓		48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓		95	Rear Bumper	Good	
22	Window Opener FL	✓		✓		49	Number of Keys	1	74	Seats	Good		96	Roof	Good	
23	Window Opener FR	✓		✓		Engine		Interior		75	Carpets	Good		97	Bonnet	Good
24	Window Opener RL	✓		✓		50	Oil Level	✓	76	Panels	Good		98	Fuel Cap	✓	
25	Window Opener RR	✓		✓		51	Smokes and Fumes	✓	77	Dashboard	Good		99	Mud Flaps	✓	
26	Rear View Mirrors	✓		✓		52	Performance	✓					100	WOF	✗	
27	Radio (Basic Test Only)	✓		✓		53	Noise	✓								
28	CD (Basic Test Only)	✓		✓		54	Starter Motor	✓								
29	Boot Open Switch	✓		✓												

Turners Certification Key:

- ✓ = Pass
- ✗ = Fail
- = Not applicable for this vehicle

Inspected by:	Blair Robertson	Date:	08 Dec 2023
---------------	-----------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--