



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,443,354
Version:	1
Created:	23 Nov 2023

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	VIN:	7AT0GF09X23197269
Year:	2019	Odometer:	74,435 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good		
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good			
4	High Stop Light	✓	Transmission and Drive		59	Steering Performance	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good			
5	Front Right Indicators	✓	34	Operation	✓	Wheels and Tyres		61	Left Front	6	mm	85	R/H Mirror	Good		
6	Front Left Indicators	✓	35	Noise	✓	62	Right Front	6	mm	63	Left Rear	6	mm	86	L/H Mirror	Good
7	Rear Right Indicators	✓	36	Clutch	•	64	Right Rear	6	mm	65	Spare	N/A	87	L/F Guard	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓	66	Tools	✓	67	AC Operation	✓	88	R/F Guard	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	Interior		68	Heater Fan	✓	89	L/H Doors	Good			
10	Rear Reflectors	✓	39	Wheel Balance	✓	69	Seatbelts	✓	70	Horn	✓	90	R/H Doors	Good		
11	Hazard Lights	✓	40	Gearbox (Manual)	• <td>71</td> <td>Seat Heaters</td> <td>•<td>72</td><td>Sun Visors</td><th>✓</th><td>91</td><td>L/H Sill</td><td>Good</td></td>	71	Seat Heaters	• <td>72</td> <td>Sun Visors</td> <th>✓</th> <td>91</td> <td>L/H Sill</td> <td>Good</td>	72	Sun Visors	✓	91	L/H Sill	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓</th> <td>74</td> <td>Seats</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	92	R/H Sill	Good		
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	75	Carpets	Good	76	Panels	Good	93	Boot/Tail Gate	Good		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		77	Dashboard	Good	78	Fuel Cap	✓	94	Front Bumper	Good		
15	Number Plate Light	✓	Brakes		44	Front Brakes	✓	79	Mud Flaps	✓	95	Rear Bumper	Good			
16	Dashboard Warning Lights	✓	45	Rear Brakes	✓	46	Handbrake	✓	80	WOF	✓	96	Roof	Good		
17	Speedo	✓	Keys and Locking		47	Central Locking	✓	81	Bonnet	Good	97	Bonnet	Good			
18	Odometer	✓	48	Remote Locking	✓	49	Number of Keys	2	82	Fuel Cap	✓	98	Fuel Cap	✓		
19	Rev Counter	✓	Engine		50	Oil Level	✓	83	Mud Flaps	✓	99	Mud Flaps	✓			
20	Fuel Gauge	✓	51	Smokes and Fumes	✓	52	Performance	✓	100	WOF	✓	100	WOF	✓		
21	Wipers Front/Rear	✓	53	Noise	✓	54	Starter Motor	✓								
22	Window Opener FL	✓														
23	Window Opener FR	✓														
24	Window Opener RL	✓														
25	Window Opener RR	✓														
26	Rear View Mirrors	✓														
27	Radio (Basic Test Only)	✓														
28	CD (Basic Test Only)	✓														
29	Boot Open Switch	✓														

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Sione Mae	Date:	23 Nov 2023
---------------	-----------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--