



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,448,926
Version:	3
Created:	14 May 2024

Make:	Nissan	Body Style:	Sedan
Model:	Fuga	VIN:	7AT0DH8GX23402070
Year:	2011	Odometer:	106,531 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good				
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good				
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good				
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good		
4	High Stop Light	✓	Transmission and Drive		Suspension		59	Steering Performance	✓	60	Shock Absorbers	✓	85	R/H Mirror	Good			
5	Front Right Indicators	✓	34	Operation	✓	61	Left Front	6.0	mm	62	Right Front	6.0	mm	86	L/H Mirror	Good		
6	Front Left Indicators	✓	35	Noise	✓	63	Left Rear	6.0	mm	64	Right Rear	6.0	mm	87	L/F Guard	Good		
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		65	Spare	Yes	66	Tools	✓	88	R/F Guard	Good		
8	Rear Left Indicators	✓	37	CV Joints	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	89	L/H Doors	Good	
9	Reversing Lights	✓	38	Wheel Bearing	✓	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	90	R/H Doors	Good	
10	Rear Reflectors	✓	39	Wheel Balance	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Average	75	Carpets	Average	91	L/H Sill	Good	
11	Hazard Lights	✓	40	Gearbox (Manual)	•	76	Panels	Average	77	Dashboard	Average	92	R/H Sill	Good	93	Boot/Tail Gate	Good	
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	78	Fuel Cap	✓	79	Mud Flaps	✓	80	WOF	✓	94	Front Bumper	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		99	Mud Flaps	✓	100	WOF	✓							
15	Number Plate Light	✓	Brakes		Interior													
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	
17	Speedo	✓	45	Rear Brakes	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•	
18	Odometer	✓	46	Handbrake	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	
19	Rev Counter	✓	Keys and Locking		Interior		70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓
20	Fuel Gauge	✓	47	Central Locking	✓	71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Average	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Average	75	Carpets	Average	
22	Window Opener FL	✓	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓	74	Seats	Average	75	Carpets	Average	76	Panels	Average	
23	Window Opener FR	✓	Engine		Interior		74	Seats	Average	75	Carpets	Average	76	Panels	Average	77	Dashboard	Average
24	Window Opener RL	✓	50	Oil Level	✓	75	Carpets	Average	76	Panels	Average	77	Dashboard	Average				
25	Window Opener RR	✓	51	Smokes and Fumes	✓	76	Panels	Average	77	Dashboard	Average							
26	Rear View Mirrors	✓	52	Performance	✓													
27	Radio (Basic Test Only)	✓	53	Noise	✓													
28	CD (Basic Test Only)	✓	54	Starter Motor	✓													
29	Boot Open Switch	✓																

Turners Certification Key:  
✓ = Pass  
✗ = Fail  
• = Not applicable for this vehicle

Inspected by:	Sione Mae	Date:	07 Dec 2023
I have read and understood this condition guide:			
Name:		Signature:	