



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,485,898
Version:	1
Created:	16 Jan 2024

Make:	Volkswagen	Body Style:	Hatchback
Model:	UP	VIN:	WVWZZZAAZFD067901
Year:	2015	Odometer:	67,819 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good									
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation				•									
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good									
3	Tail Lights	✓	33	Window Lock Switch	•	Suspension		58	Suspension Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good							
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td><td>85</td><td>R/H Mirror</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	84	Rear Wiper Blade	Good	85	R/H Mirror	Good							
5	Front Right Indicators	✓	35	Noise	✓ <td>36</td> <td>Clutch</td> <td>•</td> <td>60</td> <td>Shock Absorbers</td> <th>✓<td>86</td><td>L/H Mirror</td><td>Good</td><td>87</td><td>L/F Guard</td><td>Good</td></th>	36	Clutch	•	60	Shock Absorbers	✓ <td>86</td> <td>L/H Mirror</td> <td>Good</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	86	L/H Mirror	Good	87	L/F Guard	Good						
6	Front Left Indicators	✓	37	CV Joints	✓ <td>38</td> <td>Wheel Bearing</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>61</td><td>Left Front</td><td>6</td><td>mm</td><td>88</td><td>R/F Guard</td><td>Good</td></th>	38	Wheel Bearing	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>6</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	Wheels and Tyres		61	Left Front	6	mm	88	R/F Guard	Good						
7	Rear Right Indicators	✓	39	Wheel Balance	✓ <td>40</td> <td>Gearbox (Manual)</td> <td>•</td> <td>62</td> <td>Right Front</td> <td>6</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>6</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	40	Gearbox (Manual)	•	62	Right Front	6	mm	63	Left Rear	6	mm	89	L/H Doors	Good				
8	Rear Left Indicators	✓	41	Engine Timing	Cambelt	42	Evidence of Cam Belt Replacement	No	64	Right Rear	6	mm	65	Spare	No	90	R/H Doors	Good					
9	Reversing Lights	✓	43	Replaced at (odometer reading)		Brakes		44	Front Brakes	✓ <td>66</td> <td>Tools</td> <td>✗</td> <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	66	Tools	✗	Interior		67	AC Operation	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good		
10	Rear Reflectors	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>92</td><td>R/H Sill</td><td>Good</td></th></th></th></th>	46	Handbrake	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>92</td><td>R/H Sill</td><td>Good</td></th></th></th>	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>92</td><td>R/H Sill</td><td>Good</td></th></th>	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>92</td><td>R/H Sill</td><td>Good</td></th>	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	71	Seat Heaters	•	92	R/H Sill	Good
11	Hazard Lights	✓	Keys and Locking		47	Central Locking	✓ <td>48</td> <td>Remote Locking</td> <th>✓<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Average</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th></th></th>	48	Remote Locking	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>74</td><td>Seats</td><td>Average</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th></th>	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Average</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	74	Seats	Average	93	Boot/Tail Gate	Good	
12	Courtesy Lights	✓	49	Number of Keys	1	Engine		50	Oil Level	✓ <td>75</td> <td>Carpets</td> <td>Average</td> <td>76</td> <td>Panels</td> <td>Average</td> <td>77</td> <td>Dashboard</td> <td>Average</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	75	Carpets	Average	76	Panels	Average	77	Dashboard	Average	94	Front Bumper	Good	
13	Dashboard Lights	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td><td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><td>✓</td></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td><td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><td>✓</td></th>	53	Noise	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <td>✓</td>	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓
14	Dashboard Dimmer Switch	•	54	Starter Motor	✓ <td>99</td> <td>Mud Flaps</td> <td>✓</td> <td>100</td> <td>WOF</td> <td>✓</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	99	Mud Flaps	✓	100	WOF	✓												
15	Number Plate Light	✓																					
16	Dashboard Warning Lights	✓																					
17	Speedo	✓																					
18	Odometer	✓																					
19	Rev Counter	✓																					
20	Fuel Gauge	✓																					
21	Wipers Front/Rear	✓																					
22	Window Opener FL	✓																					
23	Window Opener FR	✓																					
24	Window Opener RL	•																					
25	Window Opener RR	•																					
26	Rear View Mirrors	✓																					
27	Radio (Basic Test Only)	✓																					
28	CD (Basic Test Only)	•																					
29	Boot Open Switch	✓																					

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	16 Jan 2024
---------------	-------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--