



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,486,144
Version:	1
Created:	16 Feb 2024

Make:	Toyota	Body Style:	Hatchback
Model:	Aqua	VIN:	7AT0H65YX23534321
Year:	2016	Odometer:	97,602 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good				
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	4.0	mm	86	L/H Mirror	Good					
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>4.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	4.0	mm	87	L/F Guard	Good					
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>4.0</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	4.0	mm	88	R/F Guard	Good					
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>4.0</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	4.0	mm	89	L/H Doors	Good					
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	N/A	66	Tools	✓	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	68	Heater Fan	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	70	Horn	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Average</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	74	Seats	Average	94	Front Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓</th> <th colspan="2">Interior</th> <td>75</td> <td>Carpets</td> <td>Average</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	46	Handbrake	✓	Interior		75	Carpets	Average	95	Rear Bumper	Good	
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>76</td> <td>Panels</td> <td>Average</td> <td>77</td> <td>Dashboard</td> <td>Average</td> <td>96</td> <td>Roof</td> <td>Good</td>	76	Panels	Average	77	Dashboard	Average	96	Roof	Good	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>78</td> <td>Fuel Cap</td> <th>✓</th> <td>79</td> <td>Bonnet</td> <td>Good</td>	49	Number of Keys	1	78	Fuel Cap	✓	79	Bonnet	Good			
18	Odometer	✓	Engine		50	Oil Level	✓ <td>80</td> <td>Mud Flaps</td> <th>✓</th> <td>81</td> <td>WOF</td> <th>✓</th> <td>97</td> <td>Fuel Cap</td> <th>✓</th>	80	Mud Flaps	✓	81	WOF	✓	97	Fuel Cap	✓	
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>98</td><td>Mud Flaps</td><th>✓</th><td>99</td><td>Mud Flaps</td><th>✓</th><td>100</td><td>WOF</td><th>✓</th></th>	52	Performance	✓ <td>98</td> <td>Mud Flaps</td> <th>✓</th> <td>99</td> <td>Mud Flaps</td> <th>✓</th> <td>100</td> <td>WOF</td> <th>✓</th>	98	Mud Flaps	✓	99	Mud Flaps	✓	100	WOF	✓
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓</th> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	54	Starter Motor	✓									
21	Wipers Front/Rear	✓															
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	•															
29	Boot Open Switch	✓															

Turners Certification Key:
✓ = Pass
✗ = Fail
• = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	18 Jan 2024
I have read and understood this condition guide:			
Name:		Signature:	