



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	24,486,205
Version:	1
Created:	18 Jan 2024

Make:	Toyota	Body Style:	Wagon
Model:	Estima	VIN:	7AT0H61YX23188633
Year:	2015	Odometer:	101,174 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•				
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive		59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good						
5	Front Right Indicators	✓	34	Operation	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good					
6	Front Left Indicators	✓	35	Noise	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>7.0</td> <td>mm</td> <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	Wheels and Tyres		61	Left Front	7.0	mm	84	Rear Wiper Blade	Good		
7	Rear Right Indicators	✓	36	Clutch	•	62	Right Front	7.0	mm	63	Left Rear	7.0	mm	85	R/H Mirror	Good
8	Rear Left Indicators	✓	37	CV Joints	✓ <td>64</td> <td>Right Rear</td> <td>7.0</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>N/A</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	7.0	mm	65	Spare	N/A	86	L/H Mirror	Good	
9	Reversing Lights	✓	38	Wheel Bearing	✓ <td>66</td> <td>Tools</td> <th>✓<td>87</td><td>L/F Guard</td><td>Good</td></th>	66	Tools	✓ <td>87</td> <td>L/F Guard</td> <td>Good</td>	87	L/F Guard	Good					
10	Rear Reflectors	✓	39	Wheel Balance	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good			
11	Hazard Lights	✓	40	Gearbox (Manual)	•	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	71	Seat Heaters	•	90	R/H Doors	Good		
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		74	Seats	Average	75	Carpets	Average	92	R/H Sill	Good		
15	Number Plate Light	✓	Brakes		76	Panels	Average	77	Dashboard	Average	93	Boot/Tail Gate	Good			
16	Dashboard Warning Lights	✓	44	Front Brakes	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td>	94	Front Bumper	Good								
17	Speedo	✓	45	Rear Brakes	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good								
18	Odometer	✓	46	Handbrake	✓ <td>96</td> <td>Roof</td> <td>Good</td>	96	Roof	Good								
19	Rev Counter	✓	Keys and Locking		97	Bonnet	Good									
20	Fuel Gauge	✓	47	Central Locking	✓ <td>98</td> <td>Fuel Cap</td> <th>✓</th>	98	Fuel Cap	✓								
21	Wipers Front/Rear	✓	48	Remote Locking	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓								
22	Window Opener FL	✓	49	Number of Keys	2	100	WOF	✓								
23	Window Opener FR	✓	Engine													
24	Window Opener RL	✓	50	Oil Level	✓ <td></td> <td></td> <td></td>											
25	Window Opener RR	✓	51	Smokes and Fumes	✓ <td></td> <td></td> <td></td>											
26	Rear View Mirrors	✓	52	Performance	✓ <td></td> <td></td> <td></td>											
27	Radio (Basic Test Only)	✓	53	Noise	✓ <td></td> <td></td> <td></td>											
28	CD (Basic Test Only)	•	54	Starter Motor	✓ <td></td> <td></td> <td></td>											
29	Boot Open Switch	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>														

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	11 Jan 2024
---------------	-------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--